

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TP/NC

Veron

WANG YANG
7 LORONG G TELOK KURAU
SINGAPORE 426171

TAX INVOICE

Repair Code : CLM18430

Date in : 18/10/2024

Vehicle Num. : SGK9788K

Model : MERCEDES BENZ GLC 250 4MATIC

Chassis/Eng# : WDC2539462F039800/27492030578963

Contact : 91883228

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BONNET 'LOGO' EMBLEM <i>New</i>	1	125.00	125.00 <i>✓</i>
FRONT BONNET (ALUMINIUM) <i>Regis</i>	1	1890.00	1,890.00 <i>+</i>
FRONT BONNET MECHANISM LOCK RH <i>new</i>	1	145.00	145.00 <i>+</i>
FRONT BUMPER <i>Deland</i>	1	1790.00	1,790.00 <i>✓</i>
FRONT BUMPER INNER FRAME BRACKET <i>Embled</i>	1	325.00	325.00 <i>✓</i>
FRONT BUMPER LOWER GRILLE <i>lit</i>	1	223.00	223.00 <i>✓</i>
FRONT BUMPER NUMBER PLATE GARNISH <i>new</i>	1	115.00	115.00 <i>+</i>
FRONT BUMPER PARKING SENSOR <i>new</i>	2	215.00	430.00 <i>✓</i>
FRONT BUMPER RH FOGLAMP GARNISH <i>lit</i>	1	125.00	125.00 <i>✓</i>
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	75.00	150.00 <i>+</i>
FRONT BUMPER SPONGE <i>Embled</i>	1	145.00	145.00 <i>✓</i>
FRONT BUMPER TOW HOOK COVER <i>new</i>	1	70.00	70.00 <i>+</i>
FRONT GRILLE 'LOGO' EMBLEM <i>New</i>	1	98.00	98.00 <i>✓</i>
FRONT GRILLE 'LOGO' EMBLEM BASE <i>new</i>	1	105.00	105.00 <i>+</i>
FRONT GRILLE (BASE) <i>Embled</i>	1	305.00	305.00 <i>✓</i>
FRONT GRILLE OUTER COVER WITH CHROME MOULDING <i>Embled</i>	1	415.00	415.00 <i>✓</i>
FRONT RH HEADLAMP <i>lit</i>	1	3725.00	3,725.00 <i>✓</i>

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

WANG YANG
7 LORONG G TELOK KURAU
SINGAPORE 426171

Contact : 91883228

TAX INVOICE

Repair Code : CLM18430

Date in : 18/10/2024

Vehicle Num. : SGK9788K

Model : MERCEDES BENZ GLC 250 4MATIC

Chassis/Eng# : WDC2539462F039800/27492030578963

	Subtotal before discount	7291	10,181.00
Percentage discount	10%		1,018.10
	Sub-total 1	6561.90	9,162.90
FRONT BUMPER CLIPS - SET	1	80.00	80.00 30
FRONT BUMPER NUMBER PLATE	1	25.00	25.00 ✓
FRONT BUMPER NUMBER PLATE HOLDER	1	50.00	50.00 +
	Subtotal before discount		155.00
Percentage discount	0%		0.00
	Sub-total 2		155.00
	Parts-total		9,317.90

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To reset system after repair works

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

880 80.00 ✓
400.00 + 500
800.00 ~~400~~
700.00 300
100.00 +

Labour Total

2,080.00

Parts & Labour Total

11,397.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*** This is a computer-generated document which requires no signature.***

page 2

Adrian C
L/S 29/10/24

03 Days

total: 7496.90
L/S : 6K ✓