



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24100509/Uqh3e2
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	15/11/2024
SINGAPORE 048583	Code:	LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SBH 138X	Veh. Inspected	GBE 6055C
Policy No.	-	Coverage	0
Claim No.	AVS24/3360	Excess	\$0.00
Assign From	GHOBI	Assign Date	29/10/2024

2. Vehicle Details

Make & Model	TOYOTA DYNA (M)	C.C	2982
Engine No.	1KD2565248	Year of Reg.	29/01/2016
Chassis No.	KDY2318022181	Colour	BLUE
Odometer	124730 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15	DUNLOP	6
L/H Front Tyre	195R15	DUNLOP	6
R/H Rear Tyre	165R13 (D)	DUNLOP	6/6
L/H Rear Tyre	165R13 (D)	DUNLOP	6/6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/10/2024	Inspection Date	29/10/2024
Survey held at	KING'S WAY AUTOMOTIVE PTE LTD - 2 KAKI BUKIT AVE 2 #01-16 SINGAPORE 417921		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days