



興利摩多汽車燒焊廠

HING LEE MOTOR CAR REPAIR & WELDER WORKS

WORKSHOP: BLK 2, UNIT 389-E WOODLANDS ROAD, YEW TEE IND. EST. S(677959)
TEL: 68945885 HP: 96363905 EMAIL: hingleemotor@yahoo.com.sg
MAILING ADDRESS: 415 WOODLANDS ST. 41, #06-165 S(730415)

Date: 29th October 2024

Re: Vehicle Repair Estimate Car Number: SDN 6327G

Accident Statements:

Date of First Submission: 28/0/2024 15:55 (SGT)

Reported by: Policy Holder & Actual Driver: LAM SOK KUAN

Car Number: **SDN 6327G**

Car Model: Nissan NOTE E-POWER 1.2L PREMIUM

Chassis Number: JN1FAAE13Z0900649

Date of Accident: 28/10/2024 07:00 (SGT)

Location: UPPER CHANGI EAST TOWARDS PIE TUAS, SINGAPORE

ACCIDENT REPORT: SA2924ASM003

Type of Accident: Collision - Change/cross lane

Details of other vehicle: Vehicle Registration No. 94297MID

Vehicle Category: Government

Auto Parts List (Nett Price)

No.	Description	Quantity	Nett Price	Cost
1	Rear Tailgate	1	\$1,352.80	Rx \$1,352.80
2	Rear Tailgate Lamp Assy RH	1	\$273.40	cva \$273.40
3	Rear "E POWER" emblem	1	\$36.40	nei \$36.40
4	Rear "NOTE" emblem	1	\$88.80	nei \$88.80
5	Rear RH Tail Lamp Assy	1	\$347.90	cva \$347.90
6	Rear RH Corner Bumper	1	\$580.60	de \$580.60
7	Rear RH Tail Lamp Panel	1	\$689.40	bt \$689.40
8	Rear RH Fender Assy	1	\$1,350.90	buc \$1,350.90
9	Rear RH Outer Fuel Tank Cover	1	\$120.90	cva \$120.90
10	Rear RH Corner Bumper Retainer	1	\$39.80	cva \$39.80
11	Rear RH Tail Lamp Lower Support	1	\$48.20	x \$48.20
12	Rear RH Door Assy	1	\$1,328.50	buc \$1,328.50

No.	Description	Quantity	Nett Price	Cost
13	Rear RH Door Outer Handle	1	\$135.00	dis ✓ \$135.00
14	Rear RH Door Inner Lock	1	\$191.90	? \$191.90
15	Rear RH Door Hinges Top	1	\$65.50	X \$65.50
16	Rear RH Door Hinges Lower	1	\$65.50	X \$65.50
17	Rear RH Door w/Strip	1	\$128.30	rel ✓ \$128.30
18	Rear RH Door Glass Outer w/Strip	1	\$147.50	X \$147.50
	rear RM wheel rim int ✓			
			Subtotal	\$6,991.30
		Discount	10.00%	\$699.13
			Total	\$6,292.17

Special Nett Items

No.	Description / Special Nett Items	Quantity	SN Price	Cost
19	Rear Glass Sealant	1	\$50.00	x \$50.00
20	1 Set Rear Bumper Clip	1	\$50.00	rel ✓ \$50.00
21	Rear Fender To Glass Sealant	1	\$30.00	rel ✓ \$30.00
			Subtotal	\$130.00
		Discount	0.00%	\$0.00
			Total	\$130.00

Labour Charge

No.	Description	Quantity	Unit Price	Cost
1	To Remove & Refit Door Glass	1	\$80.00	40 \$80.00
2	To Remove & Refit Rear Fender Top Glass	1	\$80.00	60 \$80.00
3	Rear Tailgate Glass Remove & Refit	1	\$180.00	X \$180.00
4	Rear Roof Interior Trim Board Remove & Refit	1	\$150.00	60 \$150.00

No.	Description	Quantity	Unit Price	Cost
5	Rear Seat Remove & Refit	1	\$120.00	60 \$120.00
6	Rear Fuel Tank Remove & Refit	1	\$150.00	60 \$150.00
7	Wiring Fee and Center Lock	1	\$180.00	40 \$180.00
8	Roof Lining Remove & Refit	1	\$150.00	x \$150.00
9	To Respray Paint For Damage Area	1	\$2,200.00	802 900 \$2,200.00
10	To Repair Accident Damage Portion	1	\$2,000.00	1000 \$2,000.00
11	To Remove & Refit Bumper Sensor	1	\$50.00	40 ✓ \$50.00
			Subtotal	\$5,340.00
			Total	\$5,340.00

Grand Total

1	Auto Spare Parts For Repair	1	\$6,292.17	\$6,292.17
2	Special Nett Items	1	\$130.00	\$130.00
3	Labour Charge	1	\$5,340.00	\$5,340.00
			Subtotal	\$11,762.17
			Total	\$11,762.17



Taufik 97495749 / 62563561
 WP 01/11/24 1130
 taufik@kkauto.com
 7 days

**Hing Lee Motor Car Repair
& Welder Works Signature**

- Auto Consultants hence notify
 the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance

Acknowledged by Repairer

Signature:

Date: