



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS SOMPO INSURANCE SINGAPORE PL	Ref:	CS/SMO24100511/Kqp3e2
50 RAFFLES PLACE #03-03	Date:	20/12/2024
SINGAPORE LAND TOWER SINGAPORE 048623	Code:	SMO

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBS 7570B	Veh. Inspected	FBN 2066A
Policy No.	-	Coverage	0
Claim No.	CMTD2403470/JYC	Excess	\$0.00
Assign From	JIA YI	Assign Date	29/10/2024

### 2. Vehicle Details

Make & Model	HONDA CB150R (M)	C.C	149
Engine No.	KC32E0025984	Year of Reg.	07/08/2018
Chassis No.	MLHKC2885J5025984	Colour	GREEN
Odometer	93635 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	110/70 R17	BRIDGESTONE	2
L/H Front Tyre			
R/H Rear Tyre	150/60 R17	BRIDGESTONE	3
L/H Rear Tyre			

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	22/10/2024	Inspection Date	29/10/2024
Survey held at	JOYRIDE MOTORCYCLE (PTE LTD) - 50 SERANGOON NORTH AVENUE 4 #01-24 FIRST CENTRE SINGAPORE 555856		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days