

SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY, SINGAPORE 417883

Tel: 96195936 / info@speedwerkz.biz

VEHICLE NUMBER: SNP1333H

MAKE & MODEL: MAZDA 5

Not Authorized
for
merch.
1/11/24
4/4 # 4900
Wheelphoto After repair
limited repair

BONNET	12/30	\$1,241.00	✓
FRONT BUMPER LOGO		\$61.80	✓
FRONT BUMPER	1108.20	\$1,241.00	✓
FRONT BUMPER RETAINER L/R X2	45.50	\$112.80	✓
FRONT BUMPER FOG LAMP RH		\$381.90	✓
FRONT BUMPER SIDE GRILLE RH	115.00	\$134.10	✓
FRONT BUMPER CENTRE GRILLE	282.00	\$780.30	✓
FRONT BUMPER SPONGE		\$97.20	✓
FRONT BUMPER REINFORCEMENT		\$611.30	✓
HEADLAMP RH	1615.00	\$1,631.00	✓
HEADLAMP LOWER BRACKET RH		\$98.30	X
SUPPORT PANEL	605.00	\$823.40	✓
FRONT FENDER RH		\$586.00	X
FRONT FENDER INNER SHIELD RH		\$276.90	X
FRONT RIM RH		\$849.40	X
FRONT SHOCK ABSORBER RH		\$432.70	X
FRONT KNUCKLE ARM RH		\$503.50	X
FRONT KNUCKLE ARM HUB & BEARING RH		\$286.00	X
FRONT LOWER ARM RH		\$483.00	X
FRONT STABILISER LINK RH		\$165.10	X
Washer Tank		\$171.20	✓
		\$10,967.90	
	Less 20%	\$2,193.58	
		\$8,774.32	

FRONT BUMPER CLIPS		\$60.00	30 S/N
FRONT GRILLE ASSY CLIPS		\$30.00	X
HEADLAMP RH CLIPS		\$30.00	X
FRONT FENDER INNER SHIELD RH CLIPS		\$80.00	X
FRONT TYRE RH		\$300.00	X
		\$500.00	

TO CHECK FRONT WIRING AND HEADLAMP LEVELING
 TO REMOVE AND REFIT CONDENSER, RECHARGE A/C GAS
 TO REMOVE AND REFIT RADIATOR, TOP UP COOLANT
 TO CONDUCT WHEEL ALIGNMENT
 TO REMOVE AND REPLACE FRONT RH UNDERCARRIAGE
 COMPONENTS
 TO REMOVE AND REPLACE FRONT RH TYRE AND BALANCING
 TO PROVIDE LABOUR, WORKMANSHIP
 TO SPRAY PAINT ON AFFECTED PANELS
 RUST PROOFING

	\$60.00	20
	\$150.00	100
11	\$140.00	X
11	\$120.00	X
11	\$350.00	X
11	\$80.00	X
	\$1,400.00	600
	\$1,200.00	700
	\$80.00	30
	\$3,580.00	

Total

\$12,854.32

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 6215.4
 202
 4972.32
 30
 1450
 6452.32
 202
 5261