



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: JOANNE TAN		Ref: CS/FCI24100515/Anp3e2(N) Date: 03/04/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 8077R	Veh. Inspected	KFH 241
Policy No.	D-24101861MFCT	Coverage (\$)	0.00
Claim No.	D24009487MFCT	Excess (\$)	0.00
Assign From	JOANNE TAN	Assign Date	29/10/2024
2. Vehicle Particulars & Condition			
Make & Model	HONDA ACCORD	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	PMHCR1640HD800030	Colour	WHITE
Odometer	121120 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/50 R17	MICHELIN	6 mm
L/H Front Tyre	225/50 R17	MICHELIN	6 mm
R/H Rear Tyre	225/50 R17	MICHELIN	6 mm
L/H Rear Tyre	225/50 R17	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/10/2024	Inspection Date	29/10/2024
Survey held at	UNIMOTOR COMPANY 1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT) SINGAPORE 417883		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	