

30 Oct 2024

GBL 4550 R NISSAN NV200

No	Qty	Parts Description	Estimated Parts Price
1	1	Front headlamp -LH <i>cracked</i>	\$ 865.00 <i>610</i>
2	1	Front headlamp lower garnish <i>deformed</i>	\$ 348.60
3	1	Front grille assy <i>new</i>	\$ 507.10 <i>x</i>
4	1	Front grille logo <i>new</i>	\$ 75.20 <i>+</i>
5	1	Front bumper <i>deformed</i>	\$ 640.90 <i>+</i>
6	1	Front bumper fog lamp cover <i>new</i>	\$ 91.60 <i>x</i>
7	1	Front bumper inner sponge <i>cracked</i>	\$ 280.70 <i>108</i>
8	1	Front bumper reinforcement <i>new</i>	\$ 591.90 <i>x</i>
9	1	Front bumper side retainer <i>new</i>	\$ 40.20 <i>+</i>
10	1	Front fender -LH <i>new</i>	\$ 548.80 <i>x</i>
11	1	Front fender inner shield <i>new</i>	\$ 77.10 <i>x</i>
			\$ 4,067.10
			less 10%
			\$ 406.71
			\$ 3,660.39

No	Qty	Parts Description	Estimated Parts Price
Special Nett Items			
1	1	Front bumper clip (1 set) <i>new</i>	\$ 50.00 <i>30</i>
2	1	Front fender inner shield clip (1 set) <i>new</i>	\$ 35.00 <i>+</i>
			\$ 85.00
Total parts :			\$ 3,745.39

No	Description	Labour Charges
1	To check wiring , lighting and resetting headlamps focusing.	\$ 80.00 <i>30</i>
2	To apply undercoating on repaired and replaced panel.	\$ 100.00 <i>x</i>
3	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld ; re-align body structure and damaged consistent to the accident.	\$ 1,400.00 <i>200</i>
4	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 1,300.00 <i>100</i>
Total labour :		\$ 2,880.00

LKK Auto Consultants hereby certify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total labour : \$ 2,880.00
Total parts : \$ 3,745.39
Total labour : \$ 2,880.00
Total repair cost : \$ 6,625.39

total: 1856.75
h/s: 1.5K
02 Days