

**AUTOBACS CAR CARE (SINGAPORE) PTE. LTD.**

8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)
Tel : 6702 1555 Fax : 6702 1444
Co. Reg No. : 201500047H GST No. : 201500047H
Email : st.sim@autobacs.com.sg

TO	: CHINA TAIPING (GBL1000G)	DATE	: 29-Oct-24
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
OWNER PARTICULAR			
OWNER ID	: SXXXX235D	P -	
		S -	
		L -	
VEHICLE DETAILS		TOTAL	:
VEHICLE NO.	: SLT3225B	L/S -20%	:
MODEL / MAKE	: TOYOTA COROLLA ALTIS	SUB TOTAL	:
CHASSIS NO.	: MR053REH604573601		
ACCIDENT DETAIL			
DATE	: 26-Oct-24		
TIME	: 13:35 HRS	CONTACT PERSON : MR. SIM 9844 0974	

QUOTATION SUMMARY PAGE 01**CLAIMS DETAIL : PARTS LIST**

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BONNET 1322.40 02/suc	1	\$ 1,500.00	\$ 1,500.00
2	FRONT RADIATOR GRILLE 681.50 one	1	\$ 904.00	\$ 904.00
TOTAL PRICE				\$ 1,500.00
LESS -25%				\$ (375.00)
SUB TOTAL PRICE				\$ 1,125.00

QUOTATION SUMMARY PAGE 02**CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING**

TO REMOVE FRONT BUMPER OUT TO FACILITATE REPLACEMENT OF DAMAGED PART	\$ 400.00	300	
TO RESPRAY FRONT BUMPER / Bonnet	\$ 400.00	✓	

TOTAL \$ 800.00

ESTIMATE REPORT

TOTAL PARTS COST	:	\$ 1,125.00
TOTAL LABOUR COST	:	\$ 800.00
TOTAL REPAIR COST	:	\$ 1,925.00

APPROVED DETAILS

NO. OF REPAIR DAYS :
REPAIR UNDER :
DATE / TIME OF SURVEY :
SURVEYED BY / FROM :
CONTACT NUMBER :
EMAIL ADDRESS :
DATE / TIME OF RE-SURVEY :

LKK Auto Consultants hence notify the Repairer of the following:

PART BY PART OR LUMP SUM

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authorized
11/11/24
2/5 #1700/
Amphibian rep
3 days.

P- 2003.90
252
1502.93
700
2202.93
202
1762.