

## ESTIMATE FOR SNM1014U

Prakash S/O Devakaran

Blk 50 Dorset Road

Singapore 210050

#11-124

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Vehicle & Document Information

21199 WIP No

Reg No/Reg Date

SNM1014U / 18/08/2023 II IA /III Q4I

26492080268709

W1K2130802B0960744

Date In/Mileage

Chassis No

Engine No Make/Model

MB/E 200 SEDAN

Colour/Trim

028 831 Graphite Gr/ 042 201 Leather Bla

Account No Terms Date/Time Printed CSE Operator WCV52238 CRDVCH 01/10/2024/ 13:35 KO 301 / Kerlyn Ong

Description of Goods / Services

Qty

Unit Price Disc%

Amount

A 88395101 REPAIR RIGHT FRONT FENDER

A 98261701

Customer Request

PAINT RIGHT FRONT FENDER, STAGE 3 MET/STD, BASE AND CLEAR SYSTEM 1.00

A 82471001

Z REQUESI

REMOVE/INSTALL RIGHT FRONT LAMP UNIT

M RH/ HEADLAMP UNIT

240:00 / 800.00 /

96.00 /

3989.21 / Cut

Not Applicable For Insurance Claim

Steve (LKK) 05/11/24, 4.00 pm Without Prejudice P/P Resurvey Before Spray 3 days

Confirmed & accepted by

Nett

5,125.21

9% GST on

5125.21

461.27

**Total Payable** 

5,586.48

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur. we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or chaque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

> Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sq.