



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24100519/Uvh3e2
75 BRAS BASAH ROAD	Date:	11/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKL 3Z	Veh. Inspected	SKF 9909H
Policy No.	-	Coverage	0
Claim No.	MT/1301606-002	Excess	\$0.00
Assign From	RAJESWARY	Assign Date	29/10/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ C 180 (A)	C.C	1597
Engine No.	27191031355930	Year of Reg.	12/06/2012
Chassis No.	WDD2040452A724571	Colour	WHITE
Odometer	73271 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/45R17	GOODYEAR	6
L/H Front Tyre	225/45R17	GOODYEAR	6
R/H Rear Tyre	225/45R17	GOODYEAR	6
L/H Rear Tyre	225/45R17	GOODYEAR	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/10/2024	Inspection Date	29/10/2024 (12:05)
Survey held at	HONG AUTO SERVICES 2 KAKI BUKIT AVENUE 2 #01-28 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days