

# HONG AUTO SERVICES

2 Kaki Bukit Ave 2, #01-28, Singapore 417921  
 Tel: 6747 6436 / Fax: 6746 8868 / HP: 9853 5155  
 Email: tchong4281@gmail.com

Not Authorized  
 nu  
 meras  
 29/10/24  
 2/5# 10,100  
 2 weeks photo repair  
 6 days.

Vehicle number: SKF9909H

Vehicle Made & Model: MERCEDES-BENZ C180

Qty	Part Items	Amount \$
1	Rear boot lid DD/SUC	2,236.77 ✓
1	Rear boot M/B star BMT	89.95 ✓
3	Rear boot M/B star clips @ 8.50 ALL	25.50 ✓
1	Rear boot emblem "C180" ALL	110.25 ✓
1	Rear boot emblem "KOMPRESSOR" ALL	110.25 ✓
1	Rear boot chrome moulding BMT/ALL	281.92 ✓
1	Rear boot outer handle TWI	126.20 ✓
1	Rear boot outer keyset 11	581.65 X
2	Rear boot licence lamps @ 86.55 11	173.10 X
1	Rear boot inner lock TWI	573.82 ✓
1	Rear boot inner lock cover 11	180.63 X
1	Rear boot inner trim 11	399.61 X
1	Rear boot w/strip TWI	281.81 ✓
2	Rear boot hinges - L/R @ 195.50 11	391.00 X
	Rear boot hinge covers - L/R @ 89.95 11	179.90 X
2	Rear boot stoppers @ 12.60 11	25.20 X
1	Rear boot lock striker 11	78.85 X
1	Rear bumper DIS	1,897.21 ✓
1	Rear bumper tow cover c/w bumper	42.20 X
1	Rear bumper chrome moulding - CTR CRU	281.60 ✓
2	Rear bumper chrome mouldings - L/R @ 252.06 ALL 180x2=360	504.12 ✓
1	Rear bumper top guide - CTR TWI	181.50 ✓
2	Rear bumper side guides - L/R @ 115 CRU	230.00 ✓
2	Rear bumper side retainers - L/R @ 141.50 11	283.00 X
1	Rear bumper reinforcement BMT	1,075.60 ✓
2	Rear bumper lower brackets @ 68.60 TWI	137.20 ✓
1	Rear end panel DD/BMT	2,031.60 ✓
1	Rear end panel inner member R	811.55 X
1	Rear end panel garnish TWI	281.33 ✓
1	Rear exhaust silencer 11	1,655.50 X
1	Rear exhaust insulator 11	190.65 X
1	Rear fender - LH R	2,655.60 X
2	Rear fender tail panel garnishes @ 121.60 TWI/10.11	253.20 ✓
2	Rear fender inner trims - L/R @ 481.65 11	963.30 X

Vehicle number: SKF9909H

Vehicle Made & Model: MERCEDES-BENZ C180

1	Rear floor top board	11	580.60	X
1	Rear spare tyre well	11	481.66	X
1	Rear spare tyre retainer lock	11	211.43	X
2	Rear taillamps - L/R @ 810.53	CR	1,621.06	✓
2	Rear taillamp panels - L/R @ 195.50	R	391.00	X
2	Front seat headrests - L/R @ 861.90	R	1,723.90	X
<b>Sub-total</b>			<b>24,331.22</b>	
<b>Less 10%</b>			<b>2,433.12</b>	
<b>Total List</b>			<b>21,898.10</b>	

**Special Nett Items**

1 set	Rear boot inner trim clip	11	50.00	X
1 set	Rear bumper clip	111	50.00	30 S/W
1 set	Rear no. plate	SVC	60.00	X
1 set	Rear reverse sensor - 4 pcs	Manufacturer	420.00	200 S/W
1	Rear reverse camera	11	480.00	X
1 set	Rear spare tyre well sealant	11	120.00	X
<b>Total Special Nett</b>			<b>1,180.00</b>	

**Labour Charges**

To check rear electrical wiring	80.00	20
To remove, refix rear interior trims to assist repair	120.00	60
To remove, refix rear reverse sensor / camera	80.00	30
To remove, refix rear exhaust systems	11 120.00	X
To respray undercoating	150.00	60
To remove, refix & reset headrest system	450.00	200
To respray painting & etc	1,500.00	1000
Panel beating, cut, weld, remove & replacing above parts	1,600.00	800
<b>Total Labour</b>	<b>4,100.00</b>	

**ESTIMATE PARTS & LABOUR GRAND TOTAL \$**

**27,178.10**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 2 of 2

Acknowledged by Repairer  
Signature:  
Date:

7-11368.57  
102  
10231.72  
230:  
2170  
12631.70  
202  
10120.