

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0825/2024/KS
DATE : 29-Oct-24
WIP : 36431

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 30/10/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR ALEXANDER CLEETAS ALEXANDER
ADDRESS : BLK 788D WOODLANDS CRESCENT
#06-194
SINGAPORE 734788
TELEPHONE : HP +65 96520773
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210150880-02
VEHICLE NO : **SND 2410 A**
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 9/12/2021
ENGINE NO : CZD C49840
CHASSIS NO : WAUZZZF30M1155647
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Oct-24
PLACE OF ACCIDENT : 788D WOODLANDS CRES, BLOCK 788D, SINGAPORE 734788

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SND 4210 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 800.00	
2	TO DISMANTLE AND RENEW LHS FRONT AND REAR DOORS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	
3	TO RESPRAY LHS FRONT AND REAR DOORS.	\$ 2,200.00	
4	TO CARRY OUT DIAGNOSTIC CHECK	\$ 292.00	
TOTAL LABOUR CHARGES		: \$ 5,692.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 2410 A.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR - LH	1	\$ 3,204.00	
2	FRONT DOOR OUTER SEAL - LH	1	\$ 206.00	
3	FRONT DOOR ATTACHMENT PARTS - LH	1	\$ 175.00	
4	FRONT DOOR CATCH - LH	1	\$ 150.00	
5	FRONT DOOR COVER - LH	1	\$ 318.00	
6	REAR DOOR - LH	1	\$ 3,329.00	
7	REAR DOOR OUTER SEAL - LH	1	\$ 168.00	
8	REAR DOOR ATTACHMENT PARTS - LH	1	\$ 342.00	
9	REAR DOOR CATCH - LH	1	\$ 150.00	
10	REAR DOOR HINGE UPPER PART - LH UPPER	1	\$ 53.00	
11	REAR DOOR HINGE LOWER PART - LH UPPER	1	\$ 55.00	
12	REAR DOOR HINGE UPPER PART - LH LOWER	1	\$ 55.00	
13	REAR DOOR HINGE LOWER PART - LH LOWER	1	\$ 60.00	
14	SUNDRIES		\$ 500.00	
TOTAL SPARE PARTS			\$ 8,765.00	
TOTAL LABOUR CHARGES			\$ 5,692.00	
GRAND TOTAL			\$ 14,457.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT