

REF: CS/AIG24100520/Anp3 (SND 2410A)

ASSIGNMENT

From: _____ Date: _____
 Est: _____
 OD / TP / TP RES / OD RES / EVA / INV / MV
 To in Vehicle No: _____
 at Work m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claim No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vlt: _____

Veh No: SND2410A Yr Regn: 2021, Dec
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Audi Q3 C.D. 1395
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 45478 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WAUZZZF30M1155647
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/65R17
 R: 215/65R17

(Policy Condition)

N/S	O/S

Remark: Therah had commenced its repair at the time of inspection.

Bal. or Market Value: 152K (est)
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Falken

Front Rear
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 30/10/24
 Survey held at Premium

Des. of Damages: Frt / Rear / O/S (N/S) / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>OD AIG.</u>
	<u>COE Expiry</u>
	<u>Estimate given during : Yes (✓)</u>
	<u>1st Survey : No ()</u>
	<u>MV :</u>
	<u>PV : 80.3K</u>
	<u>Nett :</u>
	<u>12/11/24 submit preli (owner withdraw claim)</u>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: _____

1) Date/Time, File Return to?

2) _____

Arcl Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

Survey Fee:

Transportation:

3 + RS. \$ _____

Photos

Printed Form:

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0825/2024/KS
DATE : 29-Oct-24
WIP : 36431

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 30/10/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR ALEXANDER CLEETAS ALEXANDER
ADDRESS : BLK 788D WOODLANDS CRESCENT
#06-194
SINGAPORE 734788
TELEPHONE : HP +65 96520773
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210150880-02
VEHICLE NO : **SND 2410 A**
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 9/12/2021
ENGINE NO : CZD C49840
CHASSIS NO : WAUZZZF30M1155647
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Oct-24
PLACE OF ACCIDENT : 788D WOODLANDS CRES, BLOCK 788D, SINGAPORE 734788

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SND 4210 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 800.00	✓
2	TO DISMANTLE AND RENEW LHS FRONT AND REAR DOORS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	1000
3	TO RESPRAY LHS FRONT AND REAR DOORS.	\$ 2,200.00	1100
4	TO CARRY OUT DIAGNOSTIC CHECK	\$ 292.00	✓
TOTAL LABOUR CHARGES		: \$ 5,692.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SND 2410 A.

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT		REMARKS
1	FRONT DOOR - LH <i>Dented</i>	1	\$	3,204.00	✓
2	FRONT DOOR OUTER SEAL - LH <i>new</i>	1	\$	206.00	✓
3	FRONT DOOR ATTACHMENT PARTS - LH <i>new</i>	1	\$	175.00	+
4	FRONT DOOR CATCH - LH <i>?</i>	1	\$	150.00	?
5	FRONT DOOR COVER - LH <i>Dented new</i>	1	\$	318.00	✓
6	REAR DOOR - LH <i>Dented</i>	1	\$	3,329.00	✓
7	REAR DOOR OUTER SEAL - LH <i>new</i>	1	\$	168.00	✓
8	REAR DOOR ATTACHMENT PARTS - LH <i>new</i>	1	\$	342.00	+
9	REAR DOOR CATCH - LH <i>?</i>	1	\$	150.00	?
10	REAR DOOR HINGE UPPER PART - LH UPPER <i>new</i>	1	\$	53.00	+
11	REAR DOOR HINGE LOWER PART - LH UPPER <i>new</i>	1	\$	55.00	+
12	REAR DOOR HINGE UPPER PART - LH LOWER <i>new</i>	1	\$	55.00	+
13	REAR DOOR HINGE LOWER PART - LH LOWER <i>new</i>	1	\$	60.00	+
14	REAR DOOR LOWER COVER - LH <i>new</i>	1	\$	304.00	✓
15	SUNDRIES <i>?</i>		\$	500.00	?
TOTAL SPARE PARTS		:	\$	9,069.00	
TOTAL LABOUR CHARGES		:	\$	5,692.00	
GRAND TOTAL		:	\$	14,761.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *30/10/24*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *We Authorised, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT