- No illegal modification(s) is allowed

Signature:

		Date:
1PC	TAILGATE 20/Sent 4633.00	\$5,500.00
1PC	TAILGATE REAR LOGO NF	\$158.00 🗶
1PC	TAILGATE 'SKODA' EMBLEM MAA	\$98.51
1PC	TAILGATE 'KODIAQ' EMBLEM ALL	\$98.51
1PC	TAILGATE WEATHERSTRIP 47	\$495.00 ×
1PC	TAILGATE INNER LOCK Su	\$655.00 ×
1PC	TAILGATE CENTRE REFLECTOR SCRICIL	\$820.00
1PC	REAR BUMPER TOP Cu7/70-	\$2,208.62
1PC	REAR BUMPER LOWER Ground	\$473.82
1PC	REAR BUMPER TOP BLACK CENTRE GARNISH A	\$257.88 🗶
2PCS	REAR BUMPER LAMPS @\$215.00	\$430.00 ×
2PCS	REAR BUMPER SIDE HOLDERS @\$148.00	\$296.00 🗴
1PC	REAR BUMPER REINFORCEMENT 3Mf	\$1,415.00
1PC	REAR BUMPER INNER TOP RETAINER CAS	\$199.80
4PCS	REAR BUMPER PDC SENSORS @\$250.00 \$	\$1,000.00 ×
1PC	REAR BUMPER PDC SENSOR WIRE 1	\$366.00 🗸
	THE PLUM APER CLIPC	\$50.00
1SET	****	\$1,400.00 🗴
1PC	REAR END PANEL TOP GARNISH MA	\$421.00 🗴
1PC	DEAD EVHALIST ASSV	\$3,215.00 X
1PC	REAR EXHAUST MOUNTING	\$60.00 ⊀
1PC	REAR EXHAUST HEAT SHIELD	\$425.00 🏸
1PC		\$980.00 ×
1PC	TAILLAMP N/S  A 1	\$2,100.00 X
1PC	REAR BLIND SPOT SENSOR UNIT A	\$23,123.14
		LESS 10% \$20,810.83
		2230 2070 42370 2333
	S.NETT	
	3.14211	
1PC	REAR WINDSCREEN SEALANT 1	\$40.00
1PC	RAER WINDSCREEN INNER SEAL ALL	\$20.00
		¢50.00.2 a
	TO CHECK WIRING	\$50.00 %
	TO DISMANTLE & REPLACED REAR PDC SENSOR	\$100.00 30
	TO TRANSFER TAILGATE MECHANISM	\$120.00 60
	TO DISMANTLE & REFIX REAR TAILGATE GLASS	\$150.00 1 20
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	√ <sub>1</sub> \$120.00 ×
	TO DISMANTLE & REPLACED REAR EXHAUST	12 \$180.00 X
	TO SPRAY PROOFING	\$100.00 30
	TO RESET & REPROGRAMME SYSTEM	\$180.00 ×
	LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,000.00 400
	TO PUTTY & SPRAY PAINTING	\$1,200.0C SVO
		781AC 8-14,070 83
	P- 99 97·26	1910/0/2