SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711 Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLT28Z/2410161	the Repairer of the following: To recurvey before/after spray pointing:
29 th October 2024	To display damaged particly in the receivery Parts prices are subject to confirmation. Third party survey is on a "Without Projection" backs.
The Manager	e No illegal modification(s) is allowed
Motor Claim Department	- Cupylomentary item(s) must be resurvered and
AIG Asia Pacific Insurance Pte L	td is subject to final approval from Insurence Congrany

CHARTIS Building
78 Shenton Way #07-16
Signature:

Singapore 079120

Date of Accident

28th October 2024

Location :

Johor Bahru Checkpoint, Malaysia

Third Party Claim Vehicle No :

SKZ 2142 T

Repair Cost For Vehicle No

SLT 28 Z Porsche Macan

Estimated Supply of Parts & Labours

No.	Particulars	Qty	Price	A	mounts	
1	Front bumper 70 10	1	2,300.00	\$	2,300.00	
2	Front bumper side retainer L&R	2	60.00	\$	120.00	X
3	Front bumper fascia fog lamp garnish LH	1	174.00	\$	174.00	X
1 se	+ Prest bumper c1.75 580 Nes		102	\$	2,594.00	
	1			20		

Labour Charges :-	Amounts
Cut out, renew, knocking & welding Front bumper, bonnet, front fender, remove & install all damage parts, straighten & re-align body	\$ 3,200.00 400
Spray painting on damage parts	\$ 1,400.00 600 \$ 50.00 20
Check all lighting after repairs	
Diagnostic check reset	17 \$ 380.00 💢
Labour Charge	\$ 5,030.00
Total Amount	\$ 7,624.00

GST will be reflected in the final bills.

Notes: -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

Not Anhourd 45 \$2500 The phe behirpy 3 tys. 6/1/25