



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: 2024-10-22 IV

Date: 06th November 2024

Our Ref: CS1/SCD24100527/Eqp3m4

M/s Singapore Civil Defence Force (MHA05)

91 Ubi Ave 4

Singapore 408827

(The Motor Claims Department)

Attn: Syabil Ismail

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SNP 1719D

INSURED VEHICLE: QX 1036M

ACCIDENT DATE: 22/10/2024

We thank you for your instruction on 28/10/2024.

We acknowledge receipt of the following documents:-

- a) Quotation of SNP 1719D from M/s Kah Motor Co Sdn Bhd.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SNP 1719D

Make & Model : Honda HRV DX-SIN CVT YM 2022

Chassis Number : JHMRV3800NS204260

2. Our finding is that the repair cost of \$416.00 (before GST) quoted by M/s Kah Motor Co Sdn Bhd is fair & reasonable.
3. We recommend that the repairs of the entire damage require about 1 (One) working days to complete.

Yours Faithfully,



CHEN TSUE YEE
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNP 1719D

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	SPRAY PAINTING ON REAR LEFT DOOR PANEL		\$416.00	\$416.00
			\$416.00	\$416.00
GRAND TOTAL			\$416.00	\$416.00
	RECOMMENDED COST OF REPAIRS			\$416.00
Report Ref No: CS1/SCD24100527/Eqp3m4				

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.