



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: YAP KIM PENG	Document No.	: SQT24002857	Page	1
	938 JURONG WEST STREET 91	Date	: 22. Oct 2024		
	#11-405	Customer No.	: *****066F		
	SINGAPORE 640938	Svc Advisor	: SUHELMI		
Registration No	: SNP1719D	Engine No	: L15ZK1104258		
Chassis No	: JHMRV3800NS204260	Date Time	: 22. Oct 2024 4:14:05 PM		
Model	: HRV DX-SIN CVT YM 2022	Surveyor Name	:		
Owner's Name	: YAP KIM PENG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 22/10/2024				

Item	Description	Qty	Unit Price	Disc %	Amount	9% GST Amount	Amount incld GST
BP01R	SPRAY PAINTING ON REAR LEFT DOOR PANEL	1	520.00	20	416.00	37.44	453.44
Sum Labor					416.00	37.44	453.44

REPAIR WILL TAKE 2-3 WORKING DAYS
NOT APPLICABLE FOR INSURANCE CLAIM

Survey By	_____	Total Amount	416.00	37.44	453.44
Date & Time	_____	Total (Inclusive of GST)			453.44
Excess	_____				
Status	_____				
Signature	_____				

Fair & reasonable
1 days

Printed on 22/10/2024 4:16:42 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.