

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 28.10.2024

TO : **INCOME** MOTOR CLAIMS DEPTS
VEHICLE NO : **SKF8383E**
MODEL : **MERCEDES E250**
DATE OF ACCIDENT : 21.10.2024
TIME OF ACCIDENT : 18:55 HOURS

Hui Rong

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID <i>Repair</i>	1	\$ 2,448.00	\$ 2,448.00
2	BOOT LID MOULDING <i>new</i>	1	\$ 369.00	\$ 369.00
3	BOOT LID LOGO <i>new</i>	1	\$ 55.00	\$ 55.00
4	BOOT LID STOPPER <i>new</i>	4	\$ 28.00	\$ 112.00
5	BOOTLID EMBLEM '7G TRONIC' <i>3 new</i>	1	\$ 120.00	\$ 120.00
6	BOOTLID EMBLEM 'E250'	1	\$ 90.00	\$ 90.00
7	BOOT LID WEATHERSTRIP <i>2 3M</i>	1	\$ 195.00	\$ 195.00
8	BOOT LID TOP LOCK <i>new</i>	1	\$ 386.00	\$ 386.00
9	BOOT LID REVERSE LAMP <i>at RH</i>	2	\$ 490.00	\$ 980.00
10	BOOT LID INSULATOR <i>new</i>	1	\$ 360.00	\$ 360.00
11	BOOT LID LOWER LOCK MOTOR <i>3M</i>	1	\$ 468.00	\$ 468.00
12	BOOT LID HINGE <i>new</i>	2	\$ 78.00	\$ 156.00
13	REAR FENDER AIR VENT PANEL <i>Repair</i>	1	\$ 568.90	\$ 568.90
14	REAR FENDER AIR VENT <i>new</i>	1	\$ 182.00	\$ 182.00
15	REAR FENDER COWLING <i>new</i>	2	\$ 238.60	\$ 477.20
16	REAR BUMPER <i>Delaid</i>	1	\$ 1,633.00	\$ 1,633.00
17	REAR BUMPER SIDE GRILLE RH <i>at</i>	1	\$ 286.50	\$ 286.50
18	REAR BUMPER DIFFUSER <i>Delaid</i>	1	\$ 685.30	\$ 685.30
19	REAR BUMPER DIFFUSER MOULDING <i>at</i>	1	\$ 358.00	\$ 358.00

490.

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKF8383E**
 MODEL : **MERCEDES E250**
 DATE OF ACCIDENT : 21.10.2024
 TIME OF ACCIDENT : 18:55 HOURS

20	REAR BUMPER TOW HOOK COVER <i>Missing</i>	1	\$ 79.00	\$ 79.00	-
21	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 60.00	\$ 120.00	+
22	REAR BUMPER CENTER FRAME <i>new</i>	1	\$ 469.00	\$ 469.00	+
23	REAR BUMPER CENTER LOWER BRACKET <i>RH Del'd</i>	2	\$ 84.00	\$ 168.00	84
24	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 878.00	\$ 878.00	✓
25	REVERSE SENSOR <i>1 piece del'd</i>	3	\$ 275.00	\$ 825.00	275
26	REVERSE SENSOR HOLDER <i>new</i>	6	\$ 69.00	\$ 414.00	150
27	REVERSE SENSOR WIRE HARNESS <i>new</i>	1	\$ 1,426.00	\$ 1,426.00	+
28	TAIL LAMP <i>At RH</i>	2	\$ 775.00	\$ 1,550.00	775
29	TAIL LAMP LOWER BRACKET <i>new</i>	2	\$ 87.00	\$ 174.00	+
30	REAR END PANEL <i>new</i>	1	\$ 1,250.00	\$ 1,250.00	+
31	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 186.00	\$ 186.00	+
32	REAR EXHAUST MUFFLER <i>new</i>	1	\$ 2,300.00	\$ 2,300.00	+
33	REAR EXHAUST INSULATOR (TOP) <i>2</i>	1	\$ 264.00	\$ 264.00	+
34	REAR EXHAUST INSULATOR (SIDE) <i>1</i>	1	\$ 250.00	\$ 250.00	+
35	REAR EXHAUST PIPE BRACKET <i>2</i>	2	\$ 286.30	\$ 572.60	+
36	REAR EXHAUST PIPE (CHROME)	2	\$ 466.00	\$ 932.00	+
37	REAR EXHAUST MOUNTING <i>✓</i>	2	\$ 58.00	\$ 116.00	+

Side Radar Module. 1610 ✓
Could

TOTAL PRICE \$ 21,903.50
 LESS 10% \$ 2,190.35
 SUB TOTAL PRICE \$ 19,713.15

7568.80
6811.92

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
2	REAR BUMPER LOWER GARNISH CLIP RH (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
3	BOOT LID SEALANT <i>3</i>	1	\$ 150.00	\$ 150.00
4	BOOT LID MOULDING CLIP (SET) <i>2</i>	1	\$ 50.00	\$ 50.00
5	BOOT LID INSULATOR CLIP (SET) <i>1</i>	1	\$ 50.00	\$ 50.00
6	BOOT LID EMBLEM 'C&C' <i>new</i>	1	\$ 80.00	\$ 80.00
7	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00

TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKF8383E**
 MODEL : **MERCEDES E250**
 DATE OF ACCIDENT : 21.10.2024
 TIME OF ACCIDENT : 18:55 HOURS

8	REAR FENDER COWLING CLIP (SET)	1	\$ 60.00	\$ 60.00
9	TAIL LAMP CLIP (SET)	1	\$ 50.00	\$ 50.00
10	REAR END PANEL TOP GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00
11	REAR END PANEL INSULATION SEAL	1	\$ 150.00	\$ 150.00

100

TOTAL \$ 810.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, KNOCK STRAIGHTEN, ADJUST GRAZE, JOIN	\$ 1,800.00	300
2	TO PUTTY, SPRAY PAINT, POLISH, WAX AFFECTED PARTS AND PANELS	\$ 1,600.00	600
3	TUFF COAT	\$ 250.00	30
4	WIRING CHECK	\$ 250.00	30
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	x
6	CONDUCT WATER LEAKAGE TEST	\$ 80.00	x
7	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 250.00	x
8	TRANSFER BOOTLID MECHANISM	\$ 80.00	x
9	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50


TO : **INCOME** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKF8383E**
 MODEL : **MERCEDES E250**
 DATE OF ACCIDENT : 21.10.2024
 TIME OF ACCIDENT : 18:55 HOURS

10	REMOVE AND REFIX REVERSE CAMERA	\$ 180.00	X
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 450.00	X

1010

TOTAL \$5,370.00

TOTAL PARTS COST : \$ 20,523.15
 TOTAL LABOUR COST : \$ 5,370.00
 TOTAL REPAIR COST : \$ 25,893.15

Adm 
 2/s 30/10/24
 05 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

Total: 7921.82

c/s: 6.3kV ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: