

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0823/2024/KS
DATE : 29-Oct-24
WIP : 36488

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/9/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR MOHAMAD RODY BIN AHMAD
ADDRESS : 113 LORONG H TELOK KURAU
#05-02
SINGAPORE 426140
TELEPHONE : HP +65 92360897
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220038366-01
VEHICLE NO : **SNE 7692 P**
MODEL CODE : AUDI A3 SEDAN 1.5 TFSI 8Y
MODEL YEAR : 29/10/2018
ENGINE NO : CZE 846132
CHASSIS NO : WAUZZZ8V2K1002778
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Oct-24
PLACE OF ACCIDENT : CTE / SLE NEAR EXIT 3

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMF 1530 U.

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N	\$ 280.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,750.00	
3	TO RESPRAY REAR BUMPER AND LHS REAR FENDER.	\$	1,750.00	
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N	\$ 292.00	
TOTAL LABOUR CHARGES		:	\$ 4,072.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 1530 U.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,615.00	
2	REAR BUMPER STICKY PAD	4	\$ 30.00	
3	REAR BUMPER FIXING PARTS	1	\$ 216.00	
4	REAR BUMPER ADAPTOR - LH	1	\$ 48.00	
5	REAR BUMPER GUIDE SECTION - LH	1	\$ 21.00	
6	REAR BUMPER LOCKING MECHANISM	2	\$ 75.00	
7	REAR BUMPER SPOILER	1	\$ 297.00	
8	REAR LIGHT REFLECTOR - LH	1	\$ 49.00	
9	REAR PARKING AID SENSOR	1	\$ 286.00	
10	REAR PARKING AID SENSOR SEAL RING	4	\$ 11.00	
11	LED TAILLIGHT - LH	1	\$ 1,094.00	
12	LED TAILLIGHT TRIM - LH	1	\$ 36.00	
13	SUNDRIES		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 5,278.00	
TOTAL LABOUR CHARGES		:	\$ 4,072.00	
GRAND TOTAL		:	\$ 9,350.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT