

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0823/2024/KS  
**DATE** : 29-Oct-24  
**WIP** : 36488

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 27/9/2024**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

**OWNER'S NAME** : MR CHONG TZE YANG CHRISTOPHER  
**ADDRESS** : 19 SHELFORD ROAD  
#09-06  
SINGAPORE 288408  
**TELEPHONE** : HP +65 98223284  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 1800125860-04  
**VEHICLE NO** : **SMF 1530 U**  
**MODEL CODE** : AUDI A3 SEDAN 1.4 TFSI 8Y  
**MODEL YEAR** : 29/10/2018  
**ENGINE NO** : CZE 846132  
**CHASSIS NO** : WAUZZZ8V2K1002778  
**MILEAGE** : KM  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 6-Nov-24  
**PLACE OF ACCIDENT** : CTE/ SLE NEAR EXIT 3

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMF 1530 U.**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$	280.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	<del>1,750.00</del> 500	
3	TO RESPRAY REAR BUMPER AND LHS REAR FENDER.	\$	<del>1,750.00</del> 1100	
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	292.00	✓
<b>TOTAL LABOUR CHARGES</b>		: \$	<u><u>4,072.00</u></u>	

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 1530 U.**

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER <i>Delint</i>	1	\$ 2,615.00	✓	2092
2	REAR BUMPER STICKY PAD <i>new</i>	4	\$ 30.00	+	
3	REAR BUMPER FIXING PARTS <i>new</i>	1	\$ 216.00	+	
4	REAR BUMPER ADAPTOR - LH	1	\$ 48.00	+	
5	REAR BUMPER GUIDE SECTION - LH	1	\$ 21.00	+	
6	REAR BUMPER LOCKING MECHANISM	2	\$ 75.00	+	
7	REAR BUMPER SPOILER	1	\$ 297.00	+	
8	REAR LIGHT REFLECTOR - LH	1	\$ 49.00	+	
9	REAR PARKING AID SENSOR	1	\$ 286.00	+	
10	REAR PARKING AID SENSOR SEAL RING <i>new</i>	4	\$ 11.00	+	
11	LED TAILLIGHT - LH <i>cut</i>	1	\$ 1,094.00	✓	875.20
12	LED TAILLIGHT TRIM - LH <i>new</i>	1	\$ 36.00	+	
13	SUNDRIES ✓ <i>nec</i>		\$ 500.00	✓	46.32
<b>TOTAL SPARE PARTS</b>		:	\$ 5,278.00		
<b>TOTAL LABOUR CHARGES</b>		:	\$ 4,072.00		
<b>GRAND TOTAL</b>		:	\$ 9,350.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**NAME**

:

Adrian Lij

**SURVEYED DATE**

:

06/11/24

**AUTHORISED DATE**

:

**EXCESS COST**

:

**LIABILITY**

:

**REMARKS**

:

are Authorised, 04 days

**PLEASE NOTE**

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT