



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS UNITED OVERSEAS INSURANCE LTD
146 ROBINSON ROAD
#02-01 UOI BUILDING SINGAPORE 068909

Ref: CS/UOI24100534/Tvp3m4

Date: 13/12/2024

Code: UOI2

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|--------------|----------------|------------|
| Insured Veh. | GBB 4646B | Veh. Inspected | SLW 4828P |
| Policy No. | - | Coverage | 0 |
| Claim No. | M11D00092411 | Excess | \$0.00 |
| Assign From | KATIE LEE | Assign Date | 30/10/2024 |

2. Vehicle Details

| | | | |
|-----------------|-------------------|--------------|------------|
| Make & Model | BMW X1 | C.C | 1499 |
| Engine No. | 34316756B38A15F | Year of Reg. | 25/08/2022 |
| Chassis No. | WBA32AA0405V30936 | Colour | BLUE |
| Odometer | 34674 KM | Steering | IN ORDER |
| Brakes | IN ORDER | General | GOOD |
| Modification(s) | RIMS: SPORTS RIM | | |

3. Conditions of Tyres

| | Size | Make | Balance (mm) |
|----------------|-----------|----------|--------------|
| R/H Front Tyre | 205/60R17 | MICHELIN | 6 |
| L/H Front Tyre | 205/60R17 | MICHELIN | 6 |
| R/H Rear Tyre | 205/60R17 | MICHELIN | 6 |
| L/H Rear Tyre | 205/60R17 | MICHELIN | 6 |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|--|-----------------|------------|
| Accident Date | 24/10/2024 | Inspection Date | 30/10/2024 |
| Survey held at | PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941 | | |

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days