

HONG AUTO SERVICES

2 Kaki Bukit Ave 2, #01-28, Singapore 417921
Tel: 6747 6436 / Fax: 6746 8868 / HP: 9853 5155
Email: tchong4281@gmail.com

Not Authorized
Mercedes
30/10/24
5 days. d/s \$ 14,600
take photo. Hk up

Vehicle number: SLR8881J

Vehicle Make & Model: MERCEDES-BENZ GLB 180

Qty	List Items	Amount \$
1	Tailgate <i>Body DO</i>	4705.82 4,881.22 ✓
1	Tailgate windshield <i>shattered</i>	1211.93 1,322.51 ✓
2	Tailgate windshield side garnishes - L/R @ 211.50 <i>See</i>	423.00 X
1	Tailgate top spoiler <i>11</i>	1,153.21 X
1	Tailgate wiper arm <i>Damage</i>	180.93 ✓
1	Tailgate wiper arm cover <i>n.s</i>	55.63 ✓
1	Tailgate wiper motor <i>Damage</i>	591.66 ✓
2	Tailgate lamps - L/R @ 551.23 <i>scr/cr 427.14x2=854.28</i>	1,102.46 ✓
2	Tailgate licence lamps @ 89.95 <i>11</i>	179.90 X
1	Tailgate opening switch <i>Damage</i>	280.63 ✓
1	Tailgate inner lock <i>Damage</i>	580.00 755.13 ✓
1	Tailgate inner top trim <i>11</i>	311.26 X
1	Tailgate inner trim board <i>cr/cr</i>	511.62 ✓
1	Tailgate w/strip <i>twr</i>	322.71 ✓
2	Tailgate hinges - L/R @ 85.50 <i>11</i>	171.00 X
2	Tailgate dampers - L/R @ 891.10 <i>11</i>	1,782.20 X
2	Tailgate stoppers - L/R @ 22.60 <i>11</i>	45.20 X
1	Tailgate M/B star <i>11</i>	89.95 ✓
1	Tailgate M/B star clips @ 8.50 <i>11</i>	25.50 ✓
1	Tailgate emblem "GLB 180" <i>11</i>	141.20 ✓
2	Taillamps - L/R @ 894.35 <i>1/scr 0/scr</i>	1,788.70 12C
2	Taillamp lower brackets - L/R @ 86.60 <i>11</i>	173.20 X
1	Rear bumper - Top <i>Dis</i>	1520.45 1,655.93 ✓
1	Rear bumper chrome plate - Top <i>Dis</i>	611.42 ✓
1	Rear bumper CTR pad <i>1/scr</i>	811.33 ✓
1	Rear bumper bottom chrome trim <i>cr</i>	1,471.43 ✓
1	Rear bumper bottom cover - CTR <i>1/scr</i>	681.62 ✓
1	Rear bumper reflector - LH <i>See</i>	112.10 X
4	Rear bumper PDC sensors - LH @ 281.33 <i>Malfunction</i>	1,125.32 2PCS
1	Rear bumper PDC sensor wire harness <i>See</i>	411.20 X
1	Rear bumper reinforcement <i>Dis</i>	1,055.90 ✓
2	Rear bumper lower brackets @ 110.20 <i>1/scr twr 0/scr</i>	220.40 12C
2	Rear bumper side retainers - L/R @ 115.60 <i>11</i>	231.20 X
1	Rear end panel <i>R</i>	1,015.60 X
1	Rear end panel trim <i>See</i>	280.93 X
1	Rear exhaust chrome trim - LH <i>scr/but</i>	485.91 ✓
1	Rear exhaust insulator <i>11</i>	281.60 X
1	Rear exhaust silencer <i>See</i>	1,895.60 X
2	Rear fender ARC garnishes - L/R @ 399.62 <i>See</i>	799.24 X

Vehicle number: SLR8881J

Vehicle Made & Model: MERCEDES-BENZ GLB 180

1	Rear foot activated sensor	<i>CNE</i>	391.23	<i>✓</i>
1	Rear fender inner trim - LH	<i>11</i>	661.59	<i>X</i>
Sub-total			30,488.37	
Less 10%			3,048.84	
Total List			27,439.53	

Special Nett Items

1 set	Rear windscreen sealant	<i>111</i>	120.00	<i>40</i>
1	Rear windshield solar film	<i>111</i>	280.00	<i>200</i>
1	Rear recorder camera	<i>811</i>	550.00	<i>X</i>
1	Rear reverse camera	<i>811</i>	420.00	<i>X</i>
1 set	Rear bumper clip	<i>111</i>	60.00	<i>40</i>
1 set	Rear no. plate	<i>5112</i>	65.00	<i>40</i>
Total Special Nett			1,495.00	

Labour Charges

To check rear electrical wiring	50.00	<i>20</i>
To remove, refix tailgate windshield	180.00	<i>120</i>
To remove, refix rear interior trims to assist repair	150.00	<i>60</i>
To vacuum, waxing and cleaning interior	<i>11</i> 180.00	<i>X</i>
To diagnose, erase fault memory after reappear	350.00	<i>80</i>
To respray undercoating	120.00	<i>30</i>
To respray painting & etc	1,400.00	<i>800</i>
Panel beating, cut, weld, remove & replacing above parts	1,500.00	<i>550</i>
Total Labour	3,930.00	

ESTIMATE PARTS & LABOUR GRAND TOTAL \$

32,864.53

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 2 of 2

P-18148.36
102
16333.53
320
1660
18313.53
212
16650.