

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

LIBERTY INSURANCE PRIVATE LIMITED
51 CLUB STREET #03-00 LIBERTY HOUSE
SINGAPORE 069428

Attention : Motor Claim Department

Contact : 62218611 Fax No. : 62241047

Estimate : ES709691

Date : 30/10/2024

Vehicle Num. : SMV6111D

Make/Model : LEXUS RX 300

Chassis/Eng# : JTJZAMCAX02083339

Accident Date : 30/10/2024

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

<i>NOT item</i>				
EST ITEMS :				
1.	1PC	TAILGATE LOGO		325.00 X
2.	1PC	TAILGATE EMBLEM - LEXUS		154.00 X
3.	1PC	TAILGATE EMBLEM - RX300		160.00 X
4.	1PC	REAR BUMPER		1,961.00 ✓
5.	2PCS	REAR BUMPER SIDE RETAINER		578.00 X
6.	1PC	REAR BUMPER LOWER		1,587.00 ✓
7.	1PC	REAR BUMPER LOWER GARNISH		658.00 ✓
8.	1PC	N/S REAR BUMPER REFLECTOR		167.00 X
9.	1PC	N/S EXHAUST CHROME		612.00 ✓
10.	4PCS	REVERSE SENSOR		2,920.00 X
11.	4PCS	REVERSE SENSOR ORING		100.00 X
12.	4PCS	REVERSE SENSOR BRACKET		180.00 X
13.	1PC	REAR BUMPER SPONGE		276.00 ✓
14.	1PC	REAR BUMPER REINFORCEMENT		1,226.00 ✓
15.	1PC	BUZZER SENSOR		228.00 X
16.	1PC	ANTENNA SENSOR		228.00 X
17.	1 PC	REAR END PANEL		1,907.00 X
18.	1 PC	REAR END PANEL GARNISH		531.00 X
19.	1 PC	N/S REAR FENDER INNER TRIM		1,275.00 X
<i>Nett</i>				
Est Total S\$:				15,073.00
10.00% Discount S\$:				1,507.30
				13,565.70

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

LIBERTY INSURANCE PRIVATE LIMITED
51 CLUB STREET #03-00 LIBERTY HOUSE
SINGAPORE 069428

Attention : Motor Claim Department
Contact : 62218611 Fax No. : 62241047

Estimate : ES709691

Date : 30/10/2024
Vehicle Num. : SMV6111D
Make/Model : LEXUS RX 300
Chassis/Eng# : JTJZAMCAX02083339
Accident Date : 30/10/2024
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1SET	SPECIAL NETT ITEMS :		
2.	1SET	REAR BUMPER CLIP <i>121</i>		40.00 <i>30</i>
3.	1 SET	REAR BUMPER RIVET <i>11</i>		60.00 <i>X</i>
4.	1 PC	REAR END PANEL GARNISH CLIP <i>11</i>		40.00 <i>X</i>
4.	1 PC	N/S REAR FENDER INNER TRIM CLIPS <i>11</i>		40.00 <i>X</i>
Special Nett Total S\$:				180.00
LABOUR :				
TO CHECK REAR PORTION WIRING				50.00 <i>20</i>
TO FIT REVERSE SENSOR IN BUMPER				50.00 <i>30</i>
TO RESET CLEARANCE SONAR USING DIAGNOSTIC SCANNER				<i>11</i> 350.00 <i>X</i>
TO RUST PROOF PANELS				<i>11</i> 250.00 <i>X</i>
TO APPLY BODY SEALANT ON BODY JOINTS				<i>11</i> 250.00 <i>X</i>
TO REMOVE/REFIT GARNISH AND TRIMS TO FACILITATE REPAIRS				300.00 <i>50</i>
TO RESET ADAS				<i>11</i> 500.00 <i>X</i>
TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, CUT/REWELD				1,000.00 <i>480</i>
REAR END PANEL, REPLACEMENT OF PARTS AND ALIGN THE SAME				1,000.00 <i>520</i>
TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA				
Labour Total S\$:				3,750.00
E. & O.E.			Total S\$:	17,495.70

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1- 4665-4
102
4198.86
30
1100
5328.86
203
4267