

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

LIBERTY INSURANCE PRIVATE LIMITED
51 CLUB STREET #03-00 LIBERTY HOUSE
SINGAPORE 069428

Attention : Motor Claim Department

Contact : 62218611 Fax No. : 62241047

Estimate : ES709691

Date : 30/10/2024

Vehicle Num. : SMV6111D

Make/Model : LEXUS RX 300

Chassis/Eng# : JTJZAMCAX02083339

Accident Date : 30/10/2024

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
<i>NOT AUTHORIZED</i> <i>has</i> <i>more</i> <i>30/10/24</i> <i>1/2 4100</i> <i>at 10/10/24</i> <i>Hdms.</i>				
<i>NOT item</i> EST ITEMS :				
1.	1PC	TAILGATE LOGO <i>11</i>		325.00 X
2.	1PC	TAILGATE EMBLEM - LEXUS <i>11</i>		154.00 X
3.	1PC	TAILGATE EMBLEM - RX300 <i>11</i>		160.00 X
4.	1PC	REAR BUMPER <i>Dis</i>		1505.30 1,961.00 ✓
5.	2PCs	REAR BUMPER SIDE RETAINER <i>11</i>	289.00	578.00 X
6.	1PC	REAR BUMPER LOWER <i>Dis / 11</i>		1087.10 1,587.00 ✓
7.	1PC	REAR BUMPER LOWER GARNISH <i>11</i>		658.00 ✓
8.	1PC	N/S REAR BUMPER REFLECTOR <i>11</i>		167.00 X
9.	1PC	N/S EXHAUST CHROME <i>11</i>		612.00 ✓
10.	4PCS	REVERSE SENSOR <i>11</i>	730.00	2,920.00 X
11.	4PCS	REVERSE SENSOR ORING <i>11</i>	25.00	100.00 X
12.	4PCS	REVERSE SENSOR BRACKET <i>11</i>	45.00	180.00 X
13.	1PC	REAR BUMPER SPONGE <i>11</i>		176.60 276.00 ✓
14.	1PC	REAR BUMPER REINFORCEMENT <i>11</i>		826.40 1,226.00 ✓
15.	1PC	BUZZER SENSOR <i>11</i>		228.00 X
16.	1PC	ANTENNA SENSOR <i>11</i>		228.00 X
17.	1 PC	REAR END PANEL <i>11</i>		1,907.00 X
18.	1 PC	REAR END PANEL GARNISH <i>11</i>		531.00 X
19.	1 PC	N/S REAR FENDER INNER TRIM <i>11</i>		1,275.00 X
<i>Nett</i> Est Total S\$:				15,073.00
10.00% Discount S\$:				1,507.30
				13,565.70

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

LIBERTY INSURANCE PRIVATE LIMITED
51 CLUB STREET #03-00 LIBERTY HOUSE
SINGAPORE 069428

Attention : Motor Claim Department
Contact : 62218611 Fax No. : 62241047

Estimate : ES709691

Date : 30/10/2024
Vehicle Num. : SMV6111D
Make/Model : LEXUS RX 300
Chassis/Eng# : JTJZAMCAX02083339
Accident Date : 30/10/2024
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1SET	SPECIAL NETT ITEMS :		
2.	1SET	REAR BUMPER CLIP <i>121</i>		40.00 <i>30</i>
3.	1 PC	REAR BUMPER RIVET <i>11</i>		60.00 <i>X</i>
4.	1 PC	REAR END PANEL GARNISH CLIP <i>11</i>		40.00 <i>X</i>
		N/S REAR FENDER INNER TRIM CLIPS <i>11</i>		40.00 <i>X</i>
Special Nett Total S\$:				180.00
LABOUR :				
		TO CHECK REAR PORTION WIRING		50.00 <i>20</i>
		TO FIT REVERSE SENSOR IN BUMPER		50.00 <i>30</i>
		TO RESET CLEARANCE SONAR USING DIAGNOSTIC SCANNER		350.00 <i>X</i>
		TO RUST PROOF PANELS	<i>11</i>	250.00 <i>X</i>
		TO APPLY BODY SEALANT ON BODY JOINTS	<i>11</i>	250.00 <i>X</i>
		TO REMOVE/REFIT GARNISH AND TRIMS TO FACILITATE REPAIRS		300.00 <i>50</i>
		TO RESET ADAS	<i>11</i>	500.00 <i>X</i>
		TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, CUT/REWELD		1,000.00 <i>480</i>
		REAR END PANEL, REPLACEMENT OF PARTS AND ALIGN THE SAME		1,000.00 <i>400</i>
		TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA		
Labour Total S\$:				3,750.00
E. & O.E.			Total S\$:	17,495.70
				=====

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1- 4665-4
102
4188.86
30
980
5208.86
235
4167