

MIRAI AUTO PERFORMANCE PTE LTD

53 UBI AVE 1 #01-33 PAYA UBI INDUSTRIAL PARK S408934

DATE: 01.11.2024

VEHICLE NO: SNQ3986E

MAKE/ MODEL: MAZDA 3

NO	DESCRIPTION	UNIT	UNIT PRICE	AMOUNT
1	FRONT BUMPER / RR / Deep cut	1	\$ 1,285.00	\$ 1,285.00
2	FRONT BUMPER SIDE RETAINER RH / RR	1	\$ 98.00	\$ 98.00
3	FRONT BUMPER SIDED GARNISH RH X	1	\$ 212.00	\$ 212.00
4	FRONT BUMPER FOGLAMP COVER RH X	1	\$ 198.00	\$ 198.00
5	FRONT HEADLIGHT RH / Deep cut	1	\$ 3,598.00	\$ 3,598.00
6	FRONT CHROME GRILL RH / Deep cut	1	\$ 258.00	\$ 258.00
6	FRONT FENDER RH X	1	\$ 798.00	\$ 798.00
				\$ 6,447.00
			LESS 10%	\$ 5,802.30
	S/ NETT ITEMS			
1	FRONT BUMPER CLIPS / NK	1 SET	\$ 80.00	\$ 80.00
3	FRONT BUMPER LOWER GRILLE CLIP X	8	\$ 6.50	\$ 52.00
2	JOINT SEALANT X	1	\$ 100.00	\$ 100.00
			TOTAL:	\$ 232.00
	LABOUR TO			
2	TO APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 100.00	\$ 100.00
3	PANEL BEAT ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
4	SPRAY PAINT ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
			TOTAL:	\$ 1,700.00

PARTS REPLACEMENT AMOUNT

\$ 5,802.30

TOTAL AMOUNT FOR LABOUR

\$ 1,932.00

TOTAL AMOUNT \$ 7,734.30

Steve (LKK)
4/11/24, 4.00pm
w L
L/S
by AC 14
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: