



WJ AUTO SERVICES
60 JALAN LAM HUAT #04-04 S(737869)

MS FIRST CAPITAL INSURANCE LTD
6 RAFFLES QUAY #42-01
HONG LEONG LEONG BUILDING
Singapore 048581
ATTN: MOTOR CLAIM DEPARTMENT

Steve (LKK)
1/11/24, 3:00pm
W L
L/S
by AC
5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: SKD228J
MODEL : MERC E250
POLICY NO :
CHASSIS WDD2073472F079603
YEAR OF MANUFACTURE :
DATE / TIME OF ACCIDENT: 26/10/2024 Time:1625HRs at SOUTH CANAL ROAD
THIRD PARTY VEHICLE NO: SHC7133T

Date: 28/09/2024
Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price	Amount
S/N			S\$	S\$
1	REAR BUMPER <i>x R</i>	1	\$ 1,462.00	\$ 1,462.00
2	REAR BUMPER RETAINER LH <i>x</i>		\$ 85.00	\$ 85.00
3	REAR BUMPER LOWER BRACKET LH <i>x</i>		\$ 398.60	\$ 398.60
4	REAR BUMPER CENTRE OUTER MOULDING <i>x</i>		\$ 515.14	\$ 515.14
5	REAR BUMER SIDE OUTER MOULDING LH <i>x</i>		\$ 342.12	\$ 342.12
6	REAR BUMPER LOWER SUPPORT RH <i>x</i>		\$ 50.84	\$ 50.84
7	REAR BUMPER SIDE RETAINER LH <i>x</i>		\$ 97.10	\$ 97.10
8	REAR BUMPER SPONGE <i>x</i>		\$ 350.00	\$ 350.00
9	REAR REINFORMENT BAR <i>x</i>		\$ 928.00	\$ 928.00
10	REAR FENDER LH <i>x R</i>		\$ 4,038.00	\$ 4,038.00
11	REAR FENDER INNER TRIM LH <i>x</i>		\$ 659.45	\$ 659.45
12	TAIL LAMP LH <i>x</i>		\$ 1,145.36	\$ 1,145.36
13	TAIL LAMP BRACKET LH <i>x</i>		\$ 323.30	\$ 323.30
14	SPARE TIRE TOP BOARD <i>x</i>		\$ 457.61	\$ 457.61
15	REAR QUARTAR GLASS RH <i>x</i>		\$ 566.00	\$ 566.00
16	REVERSE SENSOR <i>x</i>	4	\$ 280.00	\$ 1,120.00
17	REVERSE SENSOR RETAINER <i>x</i>	4	\$ 55.00	\$ 220.00
18	FRONT DOOR LH <i>/ 00</i>		\$ 3,771.00	\$ 3,771.00
19	FRONT DOOR OUTER MOULDING LH <i>/ cut</i>		\$ 289.36	\$ 289.36
20	FRONT DOOR INNER MOULDING LH <i>x</i>		\$ 287.77	\$ 287.77
21	FRONT DOOR WEATHER STRIP LH <i>/ nec</i>		\$ 291.24	\$ 291.24
22	FRONT DOOR TOP HINGE LH <i>x</i>		\$ 150.18	\$ 150.18
23	FRONT DOOR BTM HINGE LH <i>x</i>		\$ 150.18	\$ 150.18
24	FRONT DOOR LOCK LH <i>x</i>		\$ 350.26	\$ 350.26
25	FRONT DOOR WINDOW GLASS LH <i>x</i>		\$ 1,601.15	\$ 1,601.15
26	FRONT DOOR HANDLE LH <i>x</i>		\$ 265.99	\$ 265.99
27	FRONT DOOR REGULATOR LH <i>x</i>		\$ 605.83	\$ 605.83
28	FRONT DOOR SPEAKER LH <i>x</i>		\$ 351.69	\$ 351.69
29	FRONT DOOR BOARD LH <i>x</i>		\$ 1,785.41	\$ 1,785.41

30	SIDE SKIRTING LH	✓ BR		\$ 1,589.11		\$ 145.00
31	REAR ABSORBER LH	×		\$ 990.33		\$ 990.33
32	REAR TOP STOPPER LH	×		\$ 105.76		\$ 105.76
33	REAR TOP MOUNTING LH	×		\$ 322.12		\$ 322.12
34	REAR DUST COVER LH	×		\$ 36.89		\$ 36.89
35	REAR KNUCKLE LH	✓ BT		\$ 1,145.36		\$ 1,145.36
36	REAR WHEEL BEARING LH	✓ Jommed		\$ 850.66		\$ 850.66
37	REAR LOWER ARM LH	×		\$ 820.48		\$ 820.48
38	REAR CONTROL ARM LH	×		\$ 684.33		\$ 684.33

Sub-Total: 27,759.51
Less: 10% discount - 2,775.95
Total Parts after 10% discount: 24,983.56

Special Nett Items

1	ANTI-RUST COATING	✓ nec	4	80.00	30	80.00
2	REAR BUMPER CLIPS	×	1	125.00		125.00
3	REAR FENDER CLIPS	×	1	100.00		100.00
4	REAR FENDER INNER SHIELD CLIPS	×	1	100.00		100.00
5	REAR RIM LH	✓ cut	1	1,250.00		1,250.00
6	VINYL WRAP(CUSTOMIZED)	✓ nec	1	2,500.00	900	2,500.00
7	SIDE SKIRTING BODY KIT	(LH) (carbon) ✓ BR	1	1,200.00	700	1,200.00

Total Parts: 5,355.00

Labour Charges For FRONT

1	Provide skill labour to remove all damaged parts, panel beat , cut & weld if necessary and align all panel and reinstall all damaged parts.	1,500.00	500
2	Provide skill labour & material to putty all damaged parts & panel & to	1,500.00	600
3	Provide skill labour to disconnect and check electrical wiring	150.00	80
4	Reset Engine Management system with diagnostic fault	500.00	80
5	Labour for wheel alignment	200.00	80
6	Provide skill labour to remove and reinstall rear interior compartment trims to facillite repair	400.00	×
7	Provide skill labour to remove and reinstall exhaust to facillite repair	200.00	×
8	Remove and replace rear bumper sensor	150.00	×
9	Remove and Replace quarter glass to facillate repair	200.00	×
10	Provide skill labour to transfer new door mechnisiam to faciliate repair	150.00	50

Total Labour:

Total Parts & Labour:
Grand Total:

4,950.00
35,288.56
35,288.56

Estimate Repair Duration

8 days

ACCIDENT VEHICLE OF : SKD228J

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found