

not Arthur
 1/5 \$3700
 4 days
 the photo repair
 1/11/24

SOON SAN MOTOR TRADING

Blk 3006 Ubi Rd 1, #01-390 Singapore 408700

Fax: 67473546 Tel: 68414445

Email: soonsanmotor@gmail.com

To :Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG Building S,pore 079120

Accident date: 25/10/2024

Date: 29/10/2024

Estimate cost to repair vel: SNA 3010E (Mercedes GLB 200) claims under vel: GBL 8467Y.

1pce rear bumper	20/10.11	\$ 1,555.00	✓
1pce rear bumper top cover chrome	neu	370.00	✓
1pce rear bumper lower	grand /cro	815.00	✓
2pcs rear bumper reverse sensors @\$216	SU	432.00	X
1pce rear bumper lower cover chrome	CRO 955.74	1,595.00	✓
1 set 10pcs rear bumper inner clips @\$10	neu 45	100.00	✓
2pcs rear bumper reflectors @\$104	SU	208.00	X
1pc rear bumper inner top retainers	CRO 289.00	304.00	✓
1pce rear bumper reinforcement	R	720.00	X
2pcs rear bumper exhaust pipe outer chromes @\$168	0/51w1	336.00	1pc
1pce rear panel	R	688.10	X

\$ 7,123.10

Less 10%

712.30

\$ 6,410.79

To rustproof

12 200.00 X

To remove/refit rear interior to effect repair

100.00 50

To dismantle/renew reverse sensors

100.00 40

To dismantle/renew accident portion

1,200.00 400

To Spray painting

1,200.00 400

TOTAL 49,210.79

P- 4157.74
 10%
 3777.97
 890
 4667.97
 292
 3734

LKK Auto Consultants hence notify the Repairer of the following:

- To rectify before/after spray painting
- To display damaged parts for rectification
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be rectified and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: