

LEANG AUTOMOTIVE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

TP Liberty.
Veron

Vehicle No. GBG6594C (2017)

TOYOTA DYNA KDY2318017003

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER	1	\$ 748.90	\$ 748.90
2	FRONT FOG LAMP	2	\$ 386.50	\$ 773.00
3	FRONT FOG LAMP COVER	2	\$ 96.50	\$ 193.00
4	FRONT BUMPER BRACKET	2	\$ 312.70	\$ 625.40
5	FRONT BUMPER CROSS MEMBER	1	\$ 529.90	\$ 529.90
6	HEAD LAMP	2	\$ 1,080.10	\$ 2,160.20
7	FRONT GRILLE	1	\$ 598.60	\$ 598.60
8	FRONT GRILLE LOGO	1	\$ 90.20	\$ 90.20
9	FRONT PANEL	1	\$ 1,291.80	\$ 1,291.80
10	FRONT WIPER PANEL	1	\$ 476.20	\$ 476.20
11	FRONT WINDSCREEN RUBBER	1	\$ 399.40	\$ 399.40
12	FRONT CORNER PANEL	2	\$ 364.20	\$ 728.40
13	AIR CON BLOWER	1	\$ 1,572.60	\$ 1,572.60
14	AIR CON DICHARGE PIPE	1	\$ 358.90	\$ 358.90
15	AIR CON SUCTION PIPE	1	\$ 378.90	\$ 378.90

5391.60
4043.70

TOTAL PRICE \$ 10,925.40
LESS 25% \$ 2,731.35
SUB TOTAL PRICE \$ 8,194.05

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE	1	\$ 50.00	\$ 50.00
2	FRONT GRILLE CLIP (SET)	1	\$ 40.00	\$ 40.00
3	FRONT PANEL SEALANT	1	\$ 150.00	\$ 150.00
4	FRONT WINDSCREEN GLASS SEALANT	1	\$ 80.00	\$ 80.00

150

TOTAL \$ 320.00

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	\$ 1,200.00	500
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,000.00	400
3	TO SPRAY TUFF COAT	\$ 150.00	60
4	WIRING, BULB CHECKING	\$ 50.00	30
5	REMOVE & REFIX DASHBOARD	\$ 350.00	220
6	TO REMOVE AIR CON SYSTEM & TO TOP UP AIR CON GAS	\$ 300.00	200
7	REMOVE & REFIX FRONT WINDSCREEN	\$ 180.00	120

TOTAL \$ 3,230.00

1530

TOTAL PARTS COST

TOTAL LABOUR COST

TOTAL REPAIR COST

8,514.05

3,230.00

11,744.05

Leang Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 5723.70

h/s: A.S.K.

OS Rep