



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24110005/Avh3m4
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	11/12/2024
SINGAPORE 048583	Code:	LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 7933S	Veh. Inspected	GBG 6594C
Policy No.	-	Coverage	0
Claim No.	IVS24/2007	Excess	\$0.00
Assign From	CMPY	Assign Date	30/10/2024

2. Vehicle Details

Make & Model	TOYOTA DYNA	C.C	2982
Engine No.	1KD2700080	Year of Reg.	28/09/2017
Chassis No.	KDY2318028928	Colour	SILVER
Odometer	325722 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	175/75R15	YOKOHAMA	6
L/H Front Tyre	175/75R15	YOKOHAMA	6
R/H Rear Tyre	155R13	YOKOHAMA	6
L/H Rear Tyre	155R13	YOKOHAMA	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/10/2024	Inspection Date	04/11/2024
Survey held at	LEANG AUTOMOTIVE BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days