

Eurokars Services PTE LTD
 Level 5, 27A Tanjong Penjur
 info-espl@eurokars.com.sg

Entrusted Repair Contract

Repair Order Information

Repair Order Number: SV01D2677E Arrived Date: -- Estimated Completion Time: --
 Advisor Name: Lee Yao Sheng

Customer Information

Customer	License Plate	VIN	Model	Mileage
KOH TZE KIA	SNG6166M	LRW3F7FS3NC571854	2022 MODEL 3 Red Multi-Coat	

Insurance Information

Repair Order Notes

2024/10/30 02:48 pm TP Claim -ECICS

Repair Activity

Labor

#	Correction Step		Amount with Tax
1	Frame / Structural	$720 \times 1.5 = 1080$	1080 \$1,440.00

Notes: TO REMOVE & REPLACE REAR BUMPER. ALL ACCIDENT AFFECTED AREA.

2	Refinish		1600	\$2,400.00
	Notes: TO RESPRAY REAR BUMPER & BOOTLID.	@800 x 2 - 1600		
3	Mechanical / Electrical		180	\$330.00
	Notes: TO TRANSFER REVERSE SENSORS.			
4	Mechanical / Electrical		150	\$250.00
	Notes: TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			
5	Mechanical / Electrical		250	\$300.00
	Notes: TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			
6	Frame / Structural	nec	20	\$50.00
	Notes: SUNDRIES.			

Parts

#	Part Name	Part# (Non original accessories with *)	Price	Qty	Discount Amount	Amount with Tax
1	SCREW GROMMET - 5 - 7X7H-0.65-1.5 GRP - PA6 - SEAL	1116498-00-C	\$0.81	2	0% <i>ne / ✓</i>	\$1.62
2	REAR T-BADGE	1494950-00-A	\$40.74	1	0% <i>ne / ✓</i>	\$40.74
3	LIFTGATE LAMP CONNECTOR GASKET	1453384-00-A	\$13.24	2 4	0% <i>ne / ✓</i>	\$26.48 52.96
4	BODYSIDE LAMP CONNECTOR GASKET	1453382-00-A	\$13.24	2	0% <i>ne / ✓</i>	\$26.48
5	ULTRASONIC SENSOR HPFL Shrink UPA RADIAL - Sunset Red	1741485-08-A	\$178.27	1	0% <i>dis - Cipc / ✓</i>	\$178.27
6	M3 ASY RR BUMPER BEAM - EXTRUSION	1530484-00-D	\$295.42	1	0% <i>? xnn</i>	\$295.42
7	SEMS, [FL], HX, M6x18, [88], G1009[B], MAT, ADH	1484170-00-A	\$2.04	4	0% <i>ne / ✓</i>	\$8.16
8	J - NUT M6 0.5 - 3.0 MULTITHREAD	1013802-00-B	\$3.05	4	0% <i>ne / ✓</i>	\$12.20
9	REAR FASCIA - LOWER - ASSEMBLY	1103035-00-D	\$152.81	1	0% <i>X xnn</i>	\$152.81
10	U-NUT - M5 - 2 MM GRIP - STEEL - ZNFL	1108798-00-A	\$0.81	2	0% <i>ne / ✓</i>	\$1.62
11	RR FASCIA UPTD WITH PARK ASSIST BRACKTS	1083983-SC-A	\$834.94	1	0% <i>de / ✓</i>	\$834.94

Summary

Labor

Parts

Sheet Metal (SM)	\$0.00	Gross Parts	\$1,578.74
Mech/Elec (ME)	\$880.00	Other Parts	\$0.00
Frame (FR)	\$1,490.00		
Refinish (RF)	\$2,400.00		
Car Beauty	\$0.00		
			\$4436.99
		Total	\$6,348.74
		Tax Included	

The entrusting party (myself) and the motor vehicle maintenance operator hereby agree as follows on all maintenance matters under this entrustment contract and confirm as follows:

This form is a commissioned repair contract, and the final content may be changed. Please sign here and confirm the repair content.

VT Signature

SA Signature

Customer Signature

Document Generation Date: 2024/10/30 03:29 pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hg 9w1w68
4 days
01/11/24
Rezy bP part