

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0832/2024/KS
DATE : 1-Nov-24
WIP : 36727

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 5/11/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MS JEET VIJAN
ADDRESS : 50 CORONATION ROAD WEST
#03-01
ASTRID MEADOWS
SINGAPORE 269264

TELEPHONE : HP +65 90887540
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070052915-03
VEHICLE NO : **SMS 9239 R**
MODEL CODE : AUDI Q3 SPORTBACK 1.4 TFS
MODEL YEAR : 20/3/2020
ENGINE NO : CZD 890940
CHASSIS NO : WAUZZZF32L1076303
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Oct-24
PLACE OF ACCIDENT : ASTRID MEADOWS CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 9239 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00	✓
2	TO REMOVE AND TRANSFER LHS REAR DOOR MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	✓
3	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$ 1,800.00	X
4	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOFLINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,800.00	X
5	TO REMOVE AND REINSTALL REAR BUMPER. TO DISMANTLE AND RENEW LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,400.00 <i>2.5 x 500</i>	1250 ✓
6	TO RESPRAY LHS REAR DOOR, LHS REAR FENDER, REAR END PANELLING, ROOF CHANNEL, LHS SILL PANEL, DOOR ENTRANCE, DRAIN CHANNEL, LHS REAR DOOR- LOWER COVER, BOTH REAR WHEEL ARCH TRIM AND LHS REAR DOOR HANDLE.	\$ 7,200.00 <i>2 x 200 = 400</i> <i>100</i>	1850 ✓
SUBTOTAL LABOUR CHARGES		: \$ 17,960.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMS 9239 R

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RENEW LHS 1/4 GLASS AND CARRY OUT WATER SEEPAGE TEST.	S/N \$	500.00	X
8	TO INSTALL SOLAR FILM FOR LHS 1/4 GLASS.	S/N \$	400.00	X
9	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	X
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	/✓
TOTAL LABOUR CHARGES		:	\$	19,432.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMS 9239 R

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR DOOR - LH / <i>DN</i>	1	\$	3,215.00	<i>2572</i>
2	REAR DOOR OUTER SEAL - LH / <i>npc</i>	1	\$	168.00	<i>134.40</i>
3	REAR DOOR CATCH - LH / <i>✓</i>	1	\$	150.00	<i>120</i>
4	REAR DOOR HANDLE, EXTERIOR - LH / <i>CUT</i>	1	\$	240.00	<i>192</i>
5	REAR DOOR HANDLE UNDERLAY - LH / <i>X</i>	1	\$	7.00	
6	REAR DOOR HANDLE HOUSING - LH / <i>X</i>	1	\$	34.00	
7	REAR DOOR MOUNTING BAR - LH / <i>? X</i>	1	\$	186.00	
8	REAR DOOR LOWER COVER - LH / <i>CUT</i>	1	\$	413.00	<i>330</i>
9	REAR FENDER - LH / <i>X R</i>	1	\$	4,503.00	
10	REAR QUARTER GLASS - LH / <i>X</i>	1	\$	769.00	
11	PRIMER / <i>X</i>	1	\$	27.00	
12	REAR WHEEL ARCH COVER - LH / RH / <i>CUT (photo)</i>	1	\$	1,278.00	<i>1022.40</i>
13	REAR BUMPER SPOILER / <i>CUT</i>	1	\$	573.00	<i>458</i>
14	REAR CROSS REINFORCEMENT BRACKET - CENTER / <i>X</i>	1	\$	121.00	
15	REAR BUMPER BRACKET / <i>X</i>	1	\$	60.00	
16	REAR ALUMINIUM RIM LH / <i>X</i>	1	\$	1,576.00	
17	QUARTER GLASS SEALANT / <i>X</i>	S/N	\$	100.00	
18	METAL FILLER POWDER / <i>X</i>	S/N	\$	280.00	
19	ACRYLIC SEALANT / <i>X</i>	S/N	\$	180.00	
20	STONE CHIP / <i>X</i>	S/N	\$	180.00	
21	CAVITY WAX / <i>X</i>	S/N	\$	140.00	
22	SUNDRIES / <i>? ✓</i>		\$	500.00	<i>14.72</i>
TOTAL SPARE PARTS		:	\$	14,700.00	
TOTAL LABOUR CHARGES		:	\$	19,432.00	
GRAND TOTAL		:	\$	34,132.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME	:	Steve (LKK)
SURVEYED DATE	:	5/11/24, 10.30am
AUTHORISED DATE	:	
EXCESS COST	:	OD - NY AL
LIABILITY	:	Excess - ?
REMARKS	:	PIP My Bel sy, 5 days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT