

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0831/2024/KS
DATE : 1-Nov-24
WIP : 36721

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON
YOUR INSURED VEH NO : SMW 145 R**

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road
#15-00 Springleaf Tower
Singapore 079909
Attn: Motor Claims Dept

Hi Rasul

*1 day - ok - Johnny Boo
10-Dec-24*

2787.5

OWNER'S NAME : MRS NG PUI YEE
ADDRESS : 103 WEST COAST VALE
#35-02
SINGAPORE 126754
TELEPHONE : HP +65 91836960
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : P11085400R00
VEHICLE NO : **SNG 6616 G**
MODEL CODE : AUDI Q3 2.0 TFSI QU S TRONIC
MODEL YEAR : 27/6/2022
ENGINE NO : DNN 065008
CHASSIS NO : WAUZZZF38N1083906
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Oct-24
PLACE OF ACCIDENT : CLEMENTI WEST STREET

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNG 6616 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO DISMANTLE AND RENEW REAR BUMPER. RE- ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,200.00	\$ 1,100.00
2	TO RESPRAY REAR BUMPER.	\$ 1,700.00	
3	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 480.00	\$ 480.00
TOTAL LABOUR CHARGES		: \$ 4,380.00	\$ 1,580.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNG 6616 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 1,960.00	
2	REAR BUMPER FIXING PARTS	1	\$ 233.00	
3	REAR BUMPER DAMPER - LH / RH	1	\$ 48.00	
4	REAR BUMPER SPOILER	1	\$ 573.00	\$ 572.50
5	REAR BUMPER BRACKET	1	\$ 60.00	
6	REAR LIGHT REFLECTOR - LH / RH	2	\$ 98.00	
7	REAR PARKING AID SENSOR	2	\$ 572.00	
8	REAR PARKING AID SENSOR SEAL RING	4	\$ 11.00	
9	REAR REINFORCEMENT BEAM	1	\$ 797.00	
10	REAR BUMPER HOLDING STRAP - CENTER	1	\$ 135.00	
11	REAR WHEEL ARCH COVER - LH / RH	2	\$ 636.00	\$ 635.00
12	SUNDRIES		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 5,623.00	\$ 1,207.50
TOTAL LABOUR CHARGES		:	\$ 4,380.00	\$ 1,580.00
GRAND TOTAL		:	\$ 10,003.00	\$ 2,787.50

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT