



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS INCOME INSURANCE LTD 75 BRAS BASAH ROAD INCOME CENTRE SINGAPORE 189557		Ref: Date: Code:	CS/INC24110010/Unh3m4 13/11/2024 INC
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBJ 315R	Veh. Inspected	FBS 5622Z
Policy No.	-	Coverage	0
Claim No.	MT/1302037-001	Excess	\$0.00
Assign From	EILEEN LEE	Assign Date	01/11/2024
2. Vehicle Details			
Make & Model	YAMAHA XSR155	C.C	155
Engine No.	G3J6E0294754	Year of Reg.	24/05/2021
Chassis No.	MH3RG4760MK019550	Colour	SILVER
Odometer	71128 KM	Steering	DAMAGED
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres			
	Size	Make	Balance (mm)
R/H Front Tyre	110-70R17	BRIDGESTONE	6
L/H Front Tyre			
R/H Rear Tyre	140-70R17	BRIDGESTONE	6
L/H Rear Tyre			
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/10/2024	Inspection Date	01/11/2024 (10:46)
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			