

ELITE AUTO RESTORATION PTE LTD

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Reg : 202424577D

DATE : 01.11.2024

TO : **INCOME motor claim department**
VEHICLE NO : **SNA 2938K**
MODEL : **BMW 216i GT LED**
CHASSIS : **WBA2D920005E91557**
DATE OF REG : **22.12.2017**
DATE OF ACCIDENT : **28.10.2024**

Veron.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	HEADLAMP (HID) <i>NEW</i>	1	\$ 2,678.00	\$ 2,678.00
2	FRONT FENDER RH <i>Dented</i>	1	\$ 805.20	\$ 805.20
3	FRONT FENDER INNER COWLING RH <i>torn</i>	1	\$ 178.30	\$ 178.30
4	FRONT QUARTER GLASS WITH MOLDING RH <i>new</i>	1	\$ 278.50	\$ 278.50
5	SIDE MIRROR ASSY RH <i>new</i>	1	\$ 1,580.20	\$ 1,580.20
6	FRONT SPORT RIM RH <i>lit</i>	1	\$ 1,235.80	\$ 1,235.80
7	FRONT KNUCKLE ARM RH	1	\$ 752.90	\$ 752.90
8	FRONT SHOCK ABSORBER RH	1	\$ 485.90	\$ 485.90
9	FRONT WHEEL HUP WITH BEARING RH <i>NP</i>	1	\$ 498.70	\$ 498.70
10	FRONT WHEEL ABS SENSOR RH <i>new</i>	1	\$ 196.30	\$ 196.30
11	FRONT LINKAGE RH	1	\$ 98.25	\$ 98.25
12	FRONT LOWER ARM (STRAIGHT)	1	\$ 498.60	\$ 498.60
13	FRONT LOWER ARM (BENT)	1	\$ 485.70	\$ 485.70
14	SIDESKIRT RH <i>Dented</i>	1	\$ 785.30	\$ 785.30
15	FRONT DOOR RH <i>Dented</i>	1	\$ 1,275.30	\$ 1,275.30
16	FRONT DOOR INNERTRIM RH <i>torn</i>	1	\$ 785.60	\$ 785.60
17	FRONT DOOR OUTER HANDLE RH <i>new</i>	1	\$ 325.70	\$ 325.70
18	FRONT DOOR INNERLOCK RH <i>new</i>	1	\$ 523.60	\$ 523.60
19	FRONT DOOR CHECKER RH <i>new</i>	1	\$ 98.50	\$ 98.50
20	FRONT DOOR HINGES RH <i>new</i>	2	\$ 89.60	\$ 179.20
21	FRONT DOOR WEATHERSTRIP RH DOOR <i>new</i>	1	\$ 305.80	\$ 305.80
22	REAR DOOR RH <i>new</i>	1	\$ 1,265.80	\$ 1,265.80

TOTAL PRICE \$ 15,317.15
LESS 5% \$ 765.86
SUB TOTAL PRICE \$ 14,551.29

4220.50

4009.47

S/N 1000

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT WHEEL TYRE RH <i>new</i>	1	\$ 450.00	\$ 450.00
2	SIDESKIRT CLIPS (SET) <i>m</i>	1	\$ 40.00	\$ 40.00
3	FRONT FENDER INNER COWLING (SET) <i>new</i>	1	\$ 40.00	\$ 40.00
TOTAL			\$	530.00

80

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	<i>800</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	<i>900</i>
3	TUFF COAT	\$ 150.00	<i>80</i>
4	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 450.00	<i>X</i>
5	FOUR WHEEL ALIGNMENT	\$ 120.00	<i>80</i>

1880

TOTAL

\$3,120.00

*Admin L
r/s 01/11/24,
07 Days*

TOTAL PARTS COST : \$ 15,081.29
TOTAL LABOUR COST : \$ 3,120.00
TOTAL REPAIR COST : \$ 18,201.29

Supplementary : 800

total: 7749.47

*r/s: 62K
62K*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

REQUEST FOR SUPPLEMENTS PARTS

Vehicle No	SNA 2938 K	Date of Request	01.11.2024	
Vehicle Model	BMW 216I	Number of Days to Extend (If any)		
S/N	Part Description	QTY	SPECIAL NETT	TOTAL
1	VINYL WRAP	4 PORTION	1000	\$1,000.00

BW

Adrian Cj
01/11/24.