

35	BUMPER COVER BRACKET LH	Dis	1	\$ 110.93	\$ 110.93
36	BUMPER FOAM	70-1	1	\$ 110.93	\$ 110.93
37	LOWER DIFFUSER	Dis	1	\$ 492.23	\$ 492.23
38	BUMPER MOUNTING Reinforcement	1800 bent/ra	1	\$ 3,607.50	\$ 3,607.50
39	HEAD LAMP LH	9100 CAA	1	\$ 9,127.50	\$ 9,127.50
40	BONNET	4200-15 4200-11 P/Bul	1	\$ 5,800.88	\$ 5,800.88
41	HINGE RH	250-00 bent	1	\$ 300.00	\$ 300.00
42	HINGE LH	250-00 bent	1	\$ 300.00	\$ 300.00
				TOTAL PRICE	\$ 90,022.31
				SUB TOTAL PRICE	\$ 90,022.31

5%

6733731

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIPS	1	\$ 50.00	\$ 50.00
2	FRONT NUMBER PLATE	1	\$ 60.00	\$ 60.00
TOTAL				\$ 110.00

1 set

✓ SIN
40 SIN

QUOTATION SUMMARY PAGE 02
CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO LABOUR CHARGE FOR REMOVING FRONT WINDSCREEN GLASS TO FACILITATE REPLACEMENT OF DAMAGED PARTS	\$ 300.00	120	
TO LABOUR CHARGE FOR REMOVING FRONT BONNET, BOTH FRONT FENDERS, SUPPORT PANEL, BUMPER REINFORCEMENT OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS	\$ 1,200.00	1000	
TO REMOVE AND INSTALL DASHBOARD ASSY OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS	\$ 1,500.00	300	
TO LABOUR CHARGE FOR REMOVING SRS AIRBAGS AND ALL SEAT BELTS OUT TO FACILITATE REPLACEMENT OF NEW SRS AIRBAGS AND INCLUDE SETTING AND CONFIGURATION OF THE SRS AIRBAG SYSTEM BACK TO FACTORY SPECIFICATION. ALSO TO CONFIGURE AND DO DECODING ON THE ECU MANAGEMENT, ADAS & SRS AIR BAG NETWORK	\$ 2,000.00	500	
TO RESPRAY FRONT BONNET, BOTH FRONT FENDERS, FRONT BUMPER AND SUPPORT PANEL	\$ 2,500.00	1000	
TO REMOVE RADIATOR AND AIRCON CONDENSER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	\$ 300.00	refer to labour X	
TO VACCUM AND RENEW AIRCON GAS	\$ 200.00	100	
TOTAL		\$ 8,000.00	

ESTIMATE REPORT	
TOTAL PARTS COST :	\$ 90,132.31
TOTAL LABOUR COST :	\$ 8,000.00
TOTAL REPAIR COST :	\$ 98,132.31

APPROVED DETAILS

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

0. 7897731
52
7502845
90
3020
7813845
102
70,000



AUTOBACS CAR CARE (SINGAPORE) PTE. LTD.

8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)
 Tel : 6702 1555 Fax : 6702 1444
 Co. Reg No. : 201500047H GST No. : 201500047H
 Email : st.sim@autobacs.com.sg

TO	: CHINA TAIPING (SMD6081B)	DATE	: 5-Nov-24
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
OWNER PARTICULAR			
OWNER ID	: SXXXX451A	P -	_____
		S -	_____
		L -	_____
VEHICLE DETAILS			
VEHICLE NO.	: SND7572H	TOTAL :	_____
MODEL / MAKE	: VOLVO S90	L/S -20% :	_____
CHASSIS NO.	: LVYPSL1TDNP106149	SUB TOTAL :	_____
ACCIDENT DETAIL			
DATE	: 31-Oct-24		
TIME	: 10:20 HRS	CONTACT PERSON	: MR. SIM 9844 0974

SUPPLEMENTARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	HEADLAMP RH <i>CR2</i>	1	\$ 9,100.00	\$ 9,100.00
2	BONNET LOCK RH <i>Tw/Red</i>	1	\$ 290.00	\$ 290.00
3	FRONT BUMPER NOZZLE LH <i>CR</i>	1	\$ 250.00	\$ 250.00
4	AIR CON FAN ASSY <i>CR/GRM 2000</i>	1	\$ 3,500.00	\$ 3,500.00
TOTAL PRICE				\$ 13,140.00
SUB TOTAL PRICE				\$ <u>13,140.00</u>

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	13,140.00
TOTAL LABOUR COST	:	\$	-
TOTAL REPAIR COST	:	\$	<u>13,140.00</u>

APPROVED DETAILS

NO. OF REPAIR DAYS	:		DAYS
REPAIR UNDER	:	PART BY PART OR	LUMP SUM
DATE / TIME OF SURVEY	:		
SURVEYED BY / FROM	:		
CONTACT NUMBER	:		
EMAIL ADDRESS	:		
DATE / TIME OF RE-SURVEY	:		