

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

not Authorised  
mercus  
4/11/24

1/s \$22,000/  
cheapest Atty -  
6 days.

VEHICLE No: SLS 585

|      |                                     |             |         |            |   |
|------|-------------------------------------|-------------|---------|------------|---|
| 1PC  | FRONT BUMPER                        | Dis         | 1510.80 | \$1,866.00 | ✓ |
| 1PC  | FRONT BUMPER BLACK GARNISH          | Dis         | 931.70  | \$951.70   | ✓ |
| 1PC  | FRONT BUMPER SIDE GARNISH O/S       | Dis         | 299.20  | \$330.21   | ✓ |
| 1PC  | FRONT BUMPER LOWER COVER CENTRE     | Torn        | 260.00  | \$289.90   | ✓ |
| 1PC  | FRONT BUMPER UNDER COVER            | Torn        | 301.20  | \$366.80   | ✓ |
| 1PC  | FRONT BUMPER TOW COVER              | 11          |         | \$20.00    | X |
| 1PC  | FRONT BUMPER SIDE RETAINER O/S      | one         | 105.00  | \$195.00   | ✓ |
| 1PC  | FRONT BUMPER LED LAMP O/S           | one         |         | \$785.00   | ✓ |
| 1PC  | FRONT BUMPER LED LAMP COVER O/S     | twi         | 280.00  | \$380.00   | ✓ |
| 1PC  | FRONT BUMPER PDC SENSOR O/S         | mal/huton   |         | \$269.65   | ✓ |
| 1SET | FRONT BUMPER PDC SENSOR WIRE ASSY   | skewed/Torn |         | \$455.21   | ✓ |
| 1SET | FRONT BUMPER CLIPS                  | 11          |         | \$60.00    | ✓ |
| 1PC  | FRONT BUMPER SPONGE                 | Torn        | 202.00  | \$266.00   | ✓ |
| 1PC  | FRONT BUMPER REINFORCEMENT          | Bent        | 897.75  | \$997.75   | ✓ |
| 1PC  | FRONT BUMPER INNER SIDE BRACKET O/S | one         |         | \$145.20   | ✓ |
| 1PC  | FRONT BUMPER LOWER COVER            | Torn        | 180.00  | \$245.00   | ✓ |
| 1PC  | FRONT NOSE GARNISH                  | Torn        |         | \$289.90   | ✓ |
| 1PC  | HEADLAMP N/S                        | 11          |         | \$5,506.40 | X |
| 1PC  | HEADLAMP O/S                        | 320         | 4506.40 | \$5,506.40 | ✓ |
| 1PC  | HEADLAMP LOWER BRACKET O/S          | one         |         | \$98.00    | ✓ |
| 1PC  | FRONT FENDER O/S                    | Bent/Buc    | 1020.25 | \$1,120.25 | ✓ |
| 1PC  | FRONT FENDER INNER SHIELD O/S FRT   | Torn        |         | \$288.00   | ✓ |
| 1PC  | FRONT FENDER INNER SHIELD O/S REAR  | Torn        |         | \$266.00   | ✓ |
| 1SET | FRONT FENDER INNER SHIELD CLIPS O/S | 11          |         | \$50.00    | ✓ |
| 1PC  | FRONT FENDER OUTER PROTECTOR O/S    | Dis         | 322.20  | \$366.20   | ✓ |
| 1PC  | WASHER TANK                         | 11          |         | \$305.00   | X |
| 1PC  | FRONT SHOCK ABSORBER O/S            | Bent        | 754.30  | \$845.00   | ✓ |
| 1PC  | FRONT KNUCKLE ARM O/S               | Bent        | 1055.00 | \$1,255.00 | ✓ |
| 1PC  | FRONT WHEEL HUB BEARING O/S         | 11          | 516.15  | \$650.00   | ✓ |
| 1PC  | FRONT LOWER ARM O/S                 | Bent/twi    | 366.05  | \$925.00   | ✓ |
| 1PC  | FRONT TENSION STRUT O/S             | Bent/twi    |         | \$311.20   | ✓ |
| 1PC  | FRONT WISHBONE O/S                  | Bent/twi    |         | \$311.20   | ✓ |
| 1PC  | FRONT STEERING RACK ASSY            | Bent/twi    | 5734.30 | \$6,734.30 | ✓ |
| 1PC  | FRONT CROSS MEMBER ASSY             | twi/Bent    | 2680.00 | \$2,880.00 | ✓ |
| 1PC  | FRONT STABILIZER BAR                | 11          |         | \$299.00   | X |
| 1PC  | FRONT DOOR O/S                      | 11          |         | \$2,201.00 | X |
| 1PC  | FRONT DOOR INNER RUBBER O/S         | 11          |         | \$280.00   | X |
| 1SET | FRONT DOOR FRAME STICKER O/S        | 11          |         | \$60.00    | X |
| 1PC  | FRONT DOOR OUTER PILLAR O/S         | R           |         | \$925.00   | X |
| 1PC  | FRONT DOOR MIRROR ASSY O/S          | 11          |         | \$1,610.00 | X |
| 1PC  | BONNET                              | R           |         | \$2,058.45 | X |

|     |                     |    |         |             |   |
|-----|---------------------|----|---------|-------------|---|
| 1PC | BONNET LOGO         | 17 |         | \$80.00     | X |
| 1PC | BONNER LOCK O/S     | 2m | 240.00  | \$245.00    |   |
| 1PC | FRONT SUPPORT PANEL | R  |         | \$820.00    | X |
|     |                     |    |         | \$43,909.72 |   |
|     |                     |    | LESS 5% | \$41,714.24 |   |

#### S.NETT

|      |                                     |             |            |             |
|------|-------------------------------------|-------------|------------|-------------|
| 1PC  | FRONT SPORT RIM O/S                 | But/worried | \$1,200.00 | 800 s/w     |
| 1PC  | FRONT TYRE O/S                      | 2m          | \$250.00   | 602 150 s/w |
| 1SET | FRONT FENDER INNER SHIELD CLIPS O/S | 1m          | \$40.00    | ✓ s/w       |

|                                              |             |      |
|----------------------------------------------|-------------|------|
| TO CHECK WIRING                              | \$50.00     | 20   |
| TO DISMANTLE & REPLACED FRONT PDC SENSOR     | \$80.00     | 40   |
| TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE | \$580.00    | 350  |
| TO DISMANTLE & REFIX FRONT DOOR MECHANISM    | \$120.00    | X    |
| TO RESET & DIAGNOSTIC SYSTEM                 | \$200.00    | 60   |
| TO REFILL AIR CON GAS                        | \$100.00    | X    |
| TO SPRAY RUST PROOFING                       | \$100.00    | 30   |
| TO CONDUCT WHEEL ALIGNMENT                   | \$120.00    | 100  |
| LABOUR FOR PANEL BEATING & REPLACED PARTS    | \$1,000.00  | 600  |
| TO PUTTY & SPRAY PAINTING                    | \$1,800.00  | 1000 |
| TOTAL                                        | \$47,354.24 |      |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

P-25591-66  
52  
24312-08  
990  
2200  
27502.08  
202  
22001.