

ASS. REC. BY:

REF:

TP /

CS/TP 24110021 / KvH2

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

4/9

1 Rp @ 44000 Cash

(Recd 4911.65 5290)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees:

Others:

TOTAL

Veh No:

SNA 14104

Yr Regn:

06, 21

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai

Kang

C.C.

1580

Colour

M. Gray

A/C:

Insured / Std / NI / NA

Sp. Reading

238158

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMHK281 EVMA 070447

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMi /
TOYO / YOKO or

Front

Rear

R/Bal.

2

mm

R/Bal.

2

mm

L/Bal.

2

mm

L/Bal.

2

mm

D.O.A.

16/9/24

D.O.I.

1/10/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees:

Others:

TOTAL

Serve You

SMA1410Y

NOT Noted
 11/10/04 @ 4400
 Recovery After Pain

Rear tailgate

- " " emblem
- " " outer garnish
- " " reflector x2 C403.50
- " " lock
- " " inner board
- " " weather strip
- " " wireless mldg
- " " sealant
- " " bumper assy
- " " lamp RH
- " " lower
- " " lower garnish
- " " reverse sensor
- " " reinforcement
- " " end panel
- " " " " top garnish
- " " bumper tow cover

- RM \$ 1540.00 ✓
- MC \$ 55.00 ✓
- ND \$ 245.20 ✓
- OLW \$ 807.00 ✓
- ND \$ 213.70 ✓
- LM \$ 228.80 x
- LM \$ 204.20 x
- NSP \$ 116.00 x
- MC \$ 60.00 SN 40SN
- BU \$ 812.60 ✓
- CM \$ 531.00 ✓
- CM \$ 296.50 ✓
- ND \$ 126.95 ✓
- ND \$ 300.00 SN 200SN
- CM \$ 394.90 ✓
- R \$ 785.60 x
- LM \$ 135.20 x
- ND \$ 35.00 ✓

Labour

- To remove, refix, cut & weld affected parts
- To spray paint on affected parts
- To remove & refix rear wireless
- To transfer tailgate mechanism
- Check wiring
- To remove & refix reverse sensor
- To remove & refix rear garnishes
- Tuff Coat

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

- \$ 900.00 55d ✓
- \$ 900.00 65d ✓
- \$ 150.00 12d ✓
- \$ 100.00 6d ✓
- \$ 40.00 2d ✓
- \$ 80.00 5d ✓
- \$ 100.00 5d ✓
- \$ 60.00 3d ✓