

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Tan Chow Yen

Date: 05 Aug 2024

Preliminary Advice

Vehicle No	: SJL1155Z	Accident Date	: 11/06/2024
Make	: MAZDA CX-5	Policy No.	: MPC24A00047000
Assignment Date	: 25/06/2024	Excess	: S\$0.00
Date of Inspection	: 25/06/2024	Est. Duration of Repair	: 7
Inspection At	: CONVERGENCE AUTOMOTIVE PTE LTD (HQ) 39 WOODLANDS CLOSE, MEGA@WOODLANDS #01-24 SINGAPORE 737856		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,614.00	(Estimate \$13,220.50 + Supplementary \$2,393.50)
Revised Amount	:S\$	10,936.00	(Inclusive of supplementary)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	10,936.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	78,000.00
COE / PARF Rebate	:S\$	34,730.00
Salvage Value	:S\$	
Margin for Repair	:S\$	43,270.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The vehicle repair on Lump Sum basis.
Kindly approve on supplementary.