

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building 78 Shenton Way #07-16
079120

Attention : Motor Claim Department
Contact : 6419 3000

Not Authorized
as
Merak
4/11/24
1/5 #15,800
13 days.
u h p h e A b e 14

Estimate : ES709649

Date : 01/11/2024
Vehicle Num. : SLL 7838Z
Make/Model : HONDA HRV
Chassis/Eng# :
Accident Date : 30/10/2024
Claim No. :
Reference :
Policy No. :

S/N Quantity Particular Unit Price Amount S\$

LIST ITEMS :				
1.	1PC	BONNET	20/1uc	874.40
2.	1PC	BONNET INSULATOR	n1x	998.00
3.	1PC	BONNET LOCK	2w1	191.00X
4.	1PC	FRONT BUMPER	Dis	145.00
5.	2PC	FRONT BUMPER SIDE RETAINER	n1x	176.00
6.	1PC	FRONT BUMPER CENTRE GRILLE	7w1	534.80
7.	2PC	FOG LAMP	cre	798.00
8.	2PC	FOG LAMP GARNISH	7w1	40.00
9.	2PC	FOG LAMP BRACKET	n1x	80.00X
10.	1PC	RADIATOR GRILLE BASE	cre	101.00
11.	1PC	RADIATOR GRILLE OUTER	cre	198.00
12.	1PC	RADIATOR GRILLE CHROME	8fa	774.00
13.	1PC	RADIATOR GRILLE LOGO	rec	50.00
14.	1PC	FRONT BUMPER REINFORCEMENT	sup	100.00
15.	2PC	FRONT BUMPER REINFORCEMENT RUBBER	7w1	150.00X
16.	2PC	HEADLAMP	holder cre	389.00
17.	2PC	HEADLAMP LOWER BRACKET	2070.60x2=4141.20	198.00
18.	1PC	FRONT SUPPORT PANEL	sup cre	250.70
19.	2PC	HORN	cre	397.00
20.	2PC	BONNET HINGES	sup	25.00
21.	2 PC	RADIATOR AIR GUIDE	n1x	50.00
22.	1 PC	AIR CLEANER AIR DUCT	sup cre	2,397.00
			552.00	4,794.00
				98.00
				774.00
				96.00
				95.90
				85.40
				170.80X
				97.50X

CONTINUE / ...

86679

FALCON AIR AUTO SERVICES PTE LTD

Page 2 / 5

Tel No. :

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building 78 Shenton Way #07-16
079120

Attention : Motor Claim Department
Contact : 6419 3000

Estimate : ES709649

Date : 01/11/2024
Vehicle Num. : SLL 7838Z
Make/Model : HONDA HRV
Chassis/Eng# :
Accident Date : 30/10/2024
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	2 PC	FRONT FENDER <i>Rx</i>	798.00	1,596.00 X
24.	2 PC	FRONT FENDER INNER SHIELD <i>outer protectors torn</i>	158.00	316.00 ✓
25.	1 PC	FRONT BUMPER LOWER GARNISH <i>Dis</i>		298.00 ✓
26.	1 PC	FRONT SUPPORT PANEL <i>Replaced X</i>		897.00 X
27.	1PC	AIR-CON CONDENSER <i>sup holder one</i>	808.10	1,486.00 ✓
28.	1PC	RADIATOR <i>sup holder one</i>	1322.40	1,563.00 ✓
29.	1PC	AMBIENT SENSOR <i>one X</i>		97.00 X
30.	2PC	FRONT FENDER ARCH GARNISH <i>Replaced X</i>	198.00	396.00 X
31.	1PC	RADIATOR GRILLE SIDE BRACKET <i>one</i>		39.00 ✓
32.	1PC	RADIATOR GRILLE CENTRE BRACKET <i>one</i>		68.00 ✓
33.	1PC	TAILGATE <i>one</i>	934.30	1,398.00 ✓
34.	1PC	TAILGATE EMBLEM - HRV <i>one</i>	25	46.00 ✓
35.	1PC	TAILGATE EMBLEM - I-VTEC <i>one</i>	25	47.00 ✓
36.	2PC	TAILGATE LAMP <i>one</i>	394.00	788.00 ✓
37.	1PC	TAILGATE LOCK <i>one</i>		248.00 ✓
38.	1PC	TAILGATE INNER TRIM <i>one</i>	148.50	498.00 ✓
39.	1PC	TAILGATE WEATHERSTRIP <i>one</i>	107.70	179.00 ✓
40.	1SET	TAILGATE GLASS MOULDING <i>one</i>	102.00	198.00 ✓
41.	2PC	TAILLAMP <i>one</i>	798.00	1,596.00 ✓
42.	1 PC	FRONT SUPPORT PANEL TOP GARNISH <i>one</i>	110.00	287.00 ✓
43.	1PC	REAR BUMPER <i>one</i>	538.30	689.00 ✓
44.	2PC	REAR BUMPER SIDE RETAINER <i>one</i>	48.00	96.00 X
45.	1PC	REAR BUMPER UNDERCOVER <i>one</i>		198.00 ✓
46.	2PC	REAR BUMPER SIDE <i>one</i>	148.00	296.00 ✓

CONTINUE / ...

159248 /

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building 78 Shenton Way #07-16
079120

Attention : Motor Claim Department

Contact : 6419 3000

Estimate : ES709649

Date : 01/11/2024

Vehicle Num. : SLL 7838Z

Make/Model : HONDA HRV

Chassis/Eng# :

Accident Date : 30/10/2024

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
47.	1PC	TAILGATE BUZZER <i>Che ✓</i>	126.00	126.00 ✓
48.	1PC	TAILGATE LOCK ANTENNA <i>Che ✓</i>	124.00	124.00 ✓
49.	1PC	REAR END PANEL <i>hnd 100 ✓</i>	679.00	679.00 ✓
50.	1PC	REAR END PANEL GARNISH <i>7m ✓</i>	124.00	124.00 ✓
51.	1PC	SPARE TYRE PANEL <i>couped ✓</i>	973.00	973.00 ✓
52.	1PC	SPARE TYRE SPONGE <i>10-1 ✓</i>	245.00	245.00 ✓
53.	1PC	SPARE TYRE BOARD <i>reput ✓</i>	297.00	297.00 ✓
54.	2 PC	REAR FENDER INNER TRIM <i>o/s re/trim ✓</i>	421.00	842.00 ✓
55.	2 PC	REAR FENDER ARCH GARNISH <i>win ✓</i>	124.70	249.40 ✓
56.	1 PC	EXHAUST MUFFLER <i>Rx ✓</i>	897.00	897.00 X
57.	2 PC	EXHAUST MUFFLER RUBBER HANGER <i>11 X ✓</i>	174.00	174.00 X
58.	1 PC	EXHAUST MUFFLER HEATSHIELD <i>best ✓</i>	298.00	298.00 ✓
List TotalS\$:			115.00	29,337.50
20.00% Discount S\$:				5,867.50
				23,470.00
SPECIAL NETT ITEMS :				
1.	1SET	BONNET INSULATOR CLIP <i>her 30</i>	40.00	40.00 30
2.	1SET	FRONT BUMPER CLIP <i>her 30</i>	40.00	40.00 30
3.	1PC	FRONT NUMBER PLATE <i>best 40</i>	45.00	45.00 40
4.	10 PC	FRONT BUMPER LOWER GARNISH CLIPS <i>11 X</i>	5.00	50.00 X
5.	1PC	COOLANT <i>her 30</i>	40.00	40.00 30

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building 78 Shenton Way #07-16
079120

Attention : Motor Claim Department

Contact : 6419 3000

Estimate : ES709649

Date : 01/11/2024
Vehicle Num. : SLL 7838Z
Make/Model : HONDA HRV
Chassis/Eng# :
Accident Date : 30/10/2024
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
6.	1SET	FRONT FENDER ARCH GARNISH CLIP 11 X		50.00 X
7.	1PC	TAILGATE SEALANT 11 X		100.00 X
8.	1SET	TAILGATE INNER TRIM CLIP 11 30		50.00 30
9.	1PC	TAILGATE GLASS SEALANT 11 40		40.00 ✓
10.	1PC	TAILGATE GLASS INNER SEAL 11 20		80.00 20
11.	10 PC	FRONT SUPPORT PANEL TOP GARNISH CLIP 11 30	5.00	50.00 30
12.	1 PC	REAR NUMBER PLATE 51 X		45.00 X
13.	1SET	REAR BUMPER CLIP 11 30		50.00 30
14.	1SET	REAR BUMPER UNDERCOVER CLIPS 11 30		50.00 30
15.	1SET	REAR END PANEL GARNISH CLIP 11 X		50.00 X
16.	1PC	SPARE TYRE PANEL RUBBER INSULATOR 11 X		500.00 X
17.	1SET	REAR FENDER INNER TRIM CLIP 11 X		50.00 X
18.	1 SET	REVERSE SENSOR 11 200		250.00 200
19.	10 PC	REAR FENDER ARCH GARNISH CLIP 11 X	5.00	50.00 X
Special Nett Total S\$:				1,630.00
LABOUR :				
TO CHECK LIGHT AND WIRING				50.00 30
TRANSFER TAILGATE GLASS				150.00 120
TRANSFER TAILGATE MECHANISM				100.00 60
APPLY BODY SEALANT TO CAR JOINTS				150.00 X
RE-SPRAY ANTI-RUST				150.00 120
INSTALL REVERSE SENSOR				100.00 30

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building 78 Shenton Way #07-16
079120

Attention : Motor Claim Department

Contact : 6419 3000

Estimate : ES709649

Date : 01/11/2024
Vehicle Num. : SLL 7838Z
Make/Model : HONDA HRV
Chassis/Eng# :
Accident Date : 30/10/2024
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		INSTALL REVERSE CAMERA	120.00	30
		TO VACCUM,RE-OIL AND RENEW AIRCON GAS	150.00	100
		TO REMOVE INNER TRIM,GARNISH AND ETC TO FACILITATE		
		REPAIRS AND TO FIX BACK	150.00	80
		PANEL BEATING FOR FRONT PORTION	900.00	800
		PANEL BEATING FOR REAR PORTION	1,400.00	1200
		TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS	2,400.00	1800
		Labour Total S\$:		5,820.00

E. & O.E.

Total S\$: 30,920.00

=====

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p-18593-1
202
14874.48
510
4370
15803.48
202
15803.