

Not Wholesaler
11/11/2021 84800/h

LAD2410-020

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMZ1429A

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

01 NOV 2021

SMZ1429A

JTDKB3FU903093842

201603575K

TOYOTA

PRIUS GEN 4

29/10/2024

SHA9484C/MSFCI

13/4/2021

	PART
1	COVER, FRONT BUMPER
1	ABSORBER, FRONT BUMPER ENERGY
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER
1	SUPPORT, FRONT BUMPER SIDE, RH
1	SUPPORT, RADIATOR, UPPER RH
1	MOULDING, FRONT BUMPER SIDE, RH
1	COVER, FRONT BUMPER HOLE, RH
1	GRILLE SUB-ASSY, RADIATOR
1	GRILLE, RADIATOR, LOWER NO.1
1	JAR ASSY, WINDSHIELD WASHER
1	WHEEL, DISC
1	ABSORBER ASSY, SHOCK, FRONT RH
1	SUPPORT SUB-ASSY, FRONT SUSPENSION, RH
1	JOINT ASSY, LOWER BALL, FRONT RH
1	KNUCKLE, STEERING, RH
1	FENDER SUB-ASSY, FRONT RH
1	LINER, FRONT FENDER, RH
1	EMBLEM, SIDE PANEL, RH
1	UNIT ASSY, HEADLAMP, RH

	LIST	
\$	Acc/cm	653.31 ✓
\$	Sn	100.91 X
\$	Sn	902.16 A
\$	Sn	100.49 X
\$	Sn	99.33 X
\$	Sn	120.86 ✓
\$	Sn	38.22 X
\$	Sn	532.88 X
\$	Sn	224.70 X
\$	Sn	276.15 X
\$	Acc	2,554.70 ✓
\$	Sn	596.19 Z
\$	Sn	298.10 Z
\$	Sn	331.80 Z
\$	Sn	836.64 X
\$	Sn	1,236.69 X
\$	Sn	255.36 A
\$	Sn	68.88 ✓
\$	Acc	3,325.56 ✓
TOTAL	\$	12,552.93
25%	\$	3,138.23
	\$	9,414.69

Special Nett

Trans-cab Auto Services Pte Ltd**LAD2410-020**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMZ1429A

1	FRT BUMPER CLIP	\$	<i>nn</i>	65.00	<i>65.00</i>
1	FENDER LINER CLIP	\$	<i>nn</i>	65.00	<i>X</i>
1	FRT BUMPER SIDE RETAINER CLIP	\$	<i>nn</i>	65.00	<i>X</i>
TOTAL		\$		195.00	

TOTAL PARTS \$ 9,609.69**LABOUR**

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>nn</i>	250.00	<i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$		1,800.00	<i>4401</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i>	380.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>201</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		2,000.00	<i>4001</i>
To check steering geometry and computer wheel alignment	\$		220.00	<i>601</i>
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>

TOTAL \$ 4,990.00**Over All Total \$ 14,599.69****(PART-BY-PART) Repair Days****07 Days***3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: