

Date: 01/11/2024
 Vehicle No: GBL113X
 Model: TOYOTA HIACE VAN TURBO 5DR MT
 Chassis: JTFHT02P500251351-2020
 Reg.Year: 2021

Not withstanding
11 Pm @ 4900h

Third Party Insurer: CHINA TAIPING
 Third Party Veh No: GBJ7823U
 Date of Accident: 30/10/2024
 Estimator: TING AN
 Surveyor: *6 days*

Mummy After Pains

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN GLASS <i>1191</i>	1	<i>Shotton</i>	\$1,714.00
2	REAR TAILGATE <i>2051-80</i>	1	<i>By</i>	\$2,703.00
3	REAR TAILGATE "TOYOTA" EMBLEM	1	<i>na</i>	\$75.00
4	REAR TAILGATE CHROME MOULDING	1	<i>Wap</i>	\$197.00
5	REAR TAILGATE WEATHERSTRIP	1	<i>in</i>	\$395.00
6	REAR TAILGATE LOCK	1	<i>R</i>	\$350.00
7	REAR TAIL LAMP LH	1	<i>CM</i>	\$450.00
8	REAR TAIL LAMP LOWER COVER LH	1	<i>pu</i>	\$145.00
9	REAR TAIL BRACKET LH	1	<i>CM</i>	\$60.00
10	REAR BUMPER <i>599-50</i>	1	<i>By</i>	\$659.00
11	REAR BUMPER SIDE BRACKET LH	1	<i>DIT</i>	\$50.00
12	REAR END PANEL	1	<i>By</i>	\$475.00
13	REAR PANEL LH	1		REPAIR
SUB TOTAL				\$7,273.00
LESS 25%				-\$1,818.25
PARTS TOTAL				\$5,454.75

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1	<i>na</i>	\$100.00
2	REAR BUMPER CLIPS	1	<i>na</i>	\$50.00
3	REAR BUMPER REVERSE SENSOR	1	<i>na</i>	\$300.00
4	'70KM" DECAL	1	<i>na</i>	\$40.00
5	REAR TAILGATE STRIPE DECAL	1	<i>na</i>	\$100.00
S/N TOTAL				\$590.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental repairs must be resurveyed and is subject to final approval from insurance Company



Date: 01/11/2024
 Vehicle No: GBL113X
 Model: TOYOTA HIACE VAN TURBO 5DR MT
 Chassis: JTFHT02P500251351-2020
 Reg.Year: 2021

Third Party Insurer: CHINA TAIPING
 Third Party Veh No: GBJ7823U
 Date of Accident: 30/10/2024
 Estimator: TING AN
 Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$1,200.00 *Body*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR TAIL LAMP LOWER COVER LH, REAR END PANEL REAR SIDE PANEL LH & ETC.

\$1,200.00 *Body*

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$120.00 *Body*

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$100.00 *Body*

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$120.00 *Body*

LABOUR TOTAL \$2,740.00

TOTAL \$8,784.75

TING AN