

Date: 01/11/2024

Vehicle No: GBL113X

Model: TOYOTA HIACE VAN TURBO 5DR MT

Chassis: JTFHT02P500251351-2020

Reg.Year: 2021

*Not withstanding
11 hrs @ 4900hr*

Third Party Insurer: CHINA TAIPING

Third Party Veh No: GBJ7823U

Date of Accident: 30/10/2024

Estimator: TING AN

*Phanny Aste Pains
6 days*

ESTIMATE

| NO. | DESCRIPTION | QTY | UNIT S\$ | AMOUNT S\$ |
|-------------|-----------------------------------|-----|------------------|--------------|
| 1 | REAR WINDSCREEN GLASS <i>1191</i> | 1 | <i>Shattered</i> | \$1,714.00 ✓ |
| 2 | REAR TAILGATE <i>2051-80</i> | 1 | <i>By</i> | \$2,703.00 ✓ |
| 3 | REAR TAILGATE "TOYOTA" EMBLEM | 1 | <i>By</i> | \$75.00 ✓ |
| 4 | REAR TAILGATE CHROME MOULDING | 1 | <i>Wap</i> | \$197.00 ✓ |
| 5 | REAR TAILGATE WEATHERSTRIP | 1 | <i>By</i> | \$395.00 x |
| 6 | REAR TAILGATE LOCK | 1 | <i>R</i> | \$350.00 x |
| 7 | REAR TAIL LAMP LH | 1 | <i>CM</i> | \$450.00 ✓ |
| 8 | REAR TAIL LAMP LOWER COVER LH | 1 | <i>By</i> | \$145.00 ✓ |
| 9 | REAR TAIL BRACKET LH | 1 | <i>CM</i> | \$60.00 ✓ |
| 10 | REAR BUMPER <i>599-50</i> | 1 | <i>By</i> | \$659.00 ✓ |
| 11 | REAR BUMPER SIDE BRACKET LH | 1 | <i>DIT</i> | \$50.00 ✓ |
| 12 | REAR END PANEL | 1 | <i>By</i> | \$475.00 ✓ |
| 13 | REAR PANEL LH | 1 | | REPAIR ✓ |
| SUB TOTAL | | | | \$7,273.00 |
| LESS 25% | | | | -\$1,818.25 |
| PARTS TOTAL | | | | \$5,454.75 |

| NO. | SPECIAL NETT | QTY | UNIT S\$ | AMOUNT S\$ |
|-----------|----------------------------|-----|----------|----------------------|
| 1 | REAR WINDSCREEN SEALANT | 1 | | <i>By</i> \$100.00 ✓ |
| 2 | REAR BUMPER CLIPS | 1 | | <i>By</i> \$50.00 ✓ |
| 3 | REAR BUMPER REVERSE SENSOR | 1 | | <i>By</i> \$300.00 ✓ |
| 4 | '70KM" DECAL | 1 | | <i>By</i> \$40.00 ✓ |
| 5 | REAR TAILGATE STRIPE DECAL | 1 | | <i>By</i> \$100.00 ✓ |
| S/N TOTAL | | | | \$590.00 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental repairs must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch at:

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 01/11/2024
 Vehicle No: GBL113X
 Model: TOYOTA HIACE VAN TURBO 5DR MT
 Chassis: JTFHT02P500251351-2020
 Reg.Year: 2021

Third Party Insurer: CHINA TAIPING
 Third Party Veh No: GBJ7823U
 Date of Accident: 30/10/2024
 Estimator: TING AN
 Surveyor:

LABOUR CHARGES:

| | | |
|---|-------------------|------------|
| LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC. | \$1,200.00 | <i>800</i> |
| LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR TAIL LAMP LOWER COVER LH, REAR END PANEL REAR SIDE PANEL LH & ETC. | \$1,200.00 | <i>850</i> |
| LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC. | \$120.00 | <i>50</i> |
| TO TUFF KOTE & UNDERSEAL MATERIALS. | \$100.00 | <i>60</i> |
| TO CHECK WIRING & ELECTRICAL SYSTEM. | \$120.00 | <i>20</i> |
| LABOUR TOTAL | \$2,740.00 | |

| | | |
|----------------|--------------|-------------------|
| TING AN | TOTAL | \$8,784.75 |
|----------------|--------------|-------------------|

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|--|-------------------------|
| Owner ID Type: | Company |
| Owner ID: | 610C |
| Vehicle Details | |
| Vehicle No.: | GBL113X |
| Vehicle to be Exported: | Yes |
| Intended Deregistration Date: | 01 Nov 2024 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | HIACE VAN TURBO 5DR MT |
| Primary Colour: | Silver |
| Manufacturing Year: | 2020 |
| Engine No.: | 1KDB068406 |
| Chassis No.: | JTFHT02P500251351 |
| Maximum Power Output: | - |
| Open Market Value: | \$28,235.00 |
| Original Registration Date: | 24 Feb 2021 |
| First Registration Date: | 24 Feb 2021 |
| Transfer Count: | 1 |
| Actual ARF Paid: | \$1,412.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | No |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 23 Feb 2031 |
| COE Category: | C - Goods Vehicle & Bus |
| COE Period(Years): | 10 |
| PQP Paid: | \$29,629.00 |
| COE Rebate Amount: | \$18,712.00 |
| Total Rebate Amount: | \$18,712.00 |
| Message | |
| You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE. | |

The information contained herein is correct as at 01 Nov 2024

OK