



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

email | zoomautowerks@gmail.com

D.O.A : 30/10/2024

OWNER : NORFAEZAH BINTE HAMRAN

REG. NO. : SLX419H

MAKE/MODEL : LAND ROVER DISCOVERY

not Authorized
des
altering
4/1/25
P/P 8 800/
the photo attached

2 days

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMOUNT(S\$)
<u>LIST ITEMS</u>		
1	FRONT DOOR RH 11	\$ 2,890.50 X
1	REAR DOOR RH R	\$ 3,190.20 X
1	FRONT DOOR HANDLE RH 11	\$ 230.00 X
1	REAR DOOR HANDLE RH 11	\$ 230.00 X

\$	6,540.70
LESS 10%	\$ 654.07
\$	5,886.63

SPECIAL NETT ITEMS

1	FRONT DOOR RH STICKER WRAP 11	\$ 800.00 X
1	REAR DOOR RH STICKER WRAP 11	\$ 800.00 400 S/N
		\$ 1,600.00

S/N	LABOUR CHARGES	
1	To check wiring & reset headlamp focusing	\$ 11 80.00 X
2	To remove & refit door trims	\$ 11 450.00 X
3	To conduct wheel alignment	\$ 11 180.00 X
4	To apply undercoating	\$ 11 150.00 X
5	Panel Beating	\$ 800.00 200
6	To re-spray the affected areas	\$ 800.00 200

\$	2,460.00
\$	9,946.63

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: