

## QUOTATION

CODE: F0001  
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD  
 ADDRESS: 16 RAFFLES QUAY  
 #42-01  
 HONG LEONG BUILDING  
 SINGAPORE 048581  
 ATTN:MOTOR CLAIM DEPT  
 CONTACT NO.: 65073846  
 MODEL: PORSCHE TAYCAN  
 CHASSIS NO.: WP0ZZY1ZMSA01649  
 ENGINE NO.: EBF031782  
 REG NO.: SNT3163Y  
 REGN DATE: 09/07/2021

PAGE NO.: 1  
 DOCUMENT NO.: 662  
 DOCUMENT DATE: 28/10/2024  
 POS ID:ES  
 PRINTED BY: Muhammad Nur Faiz  
 SERVICE ADV:  
 CSP/OP CODE: Muhammad Nur Faiz  
 DEPT: W  
 WIP NO.: 31553  
 REF. NO.:  
 DATE IN:  
 EXT. WTY:  
 MILEAGE: 0

DESCRIPTION: Body & Upholstery

Item	Description	Qty.	Unit Price	Stk/Status	Gross	GST
					amount	Code
			SGD		SGD	
NOTES	TP CLAIM - FIRST CAPITAL INSURANCE DOA:25/10/2024	0.00	0.00		0.00	O
INS-PANEL	TO REMOVE /REPLACE SIDE MIRROR RH, FRONT FENDER RH & ALL ACCIDENT DAMAGED BODY PARTS.TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	5,160.00	1.00		5,160.00	S
INS-PAINT-(L)	TO RESPRAY SIDE MIRROR RH, FRONT FENDER RH,FRONT BUMPER.	3,300.00	1.00		3,300.00	S
INS-PB-(L)	TO CARRY-OUT BODY CAVITY PRESERVATION.	250.00	1.00		250.00	S
INS-PB-(L)	TO REPLACE 1 PC TYRE FRONT RH.	1,200.00	1.00		1,200.00	S
INS-PB-(L)	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING.	120.00	1.00		120.00	S
INS-PB-(L)	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	680.00	1.00		680.00	S
INS-PB-(L)	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	250.00	1.00		250.00	S
INS-PB-(L)	TO ISOLATE THE EV BATTERY DURING THE REPAIRS INCLUDING CHARGING OF BATTERY.	390.00	1.00		390.00	S
INS-PB-(L)	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	600.00	1.00		600.00	S
INS-PB-(L)	SUNDRIES.	250.00	1.00		250.00	S
992-857-528-G -G2X SIDE MIRROR COVER RH		1.00	361.90		361.90	S

\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

\*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of S180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

\*This estimate is valid for a period of thirty (30) days only.

\*Prices are subject to change without prior notice.

## QUOTATION

**CODE:** F0001  
**CUSTOMER:** MS FIRST CAPITAL INSURANCE LTD  
**ADDRESS:** 16 RAFFLES QUAY  
**#42-01**  
**HONG LEONG BUILDING**  
**SINGAPORE 048581**  
**ATTN:MOTOR CLAIM DEPT**  
**CONTACT NO.:** 65073846  
**MODEL:** PORSCHE TAYCAN  
**CHASSIS NO.:** WP0ZZZY1ZMSA01649  
**ENGINE NO.:** EBF031782  
**REG NO.:** SNT3163Y  
**REGN DATE:** 09/07/2021

**PAGE NO.:** 2  
**DOCUMENT NO.:** 662  
**DOCUMENT DATE:** 28/10/2024  
**POS ID:** ES  
**PRINTED BY:** Muhammad Nur Faiz  
**SERVICE ADV:** Muhammad Nur Faiz  
**CSP/OP CODE:** W  
**DEPT:** 31553  
**WIP NO.:** 0  
**REF. NO.:**  
**DATE IN:**  
**EXT. WTY:**  
**MILEAGE:**

**DESCRIPTION:** Body & Upholstery

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
992-857-110- -OK1	SIDE MIRROR TRIM RH	1.00	434.20		434.20	S
9J1-857-578- -OK1	SIDE MIRROR BASE COVER RH	1.00	113.00		113.00	S
992-857-538-G -OK1	SIDE MIRROR COVER LOWER RH	1.00	217.00		217.00	S
992-857-522-G -	SIDE MIRROR GLASS RH	1.00	796.00		796.00	S
9J1-857-412-C -	SIDE MIRROR BASE RH	1.00	1,025.20		1,025.20	S
992-972-235-AN-	Wiring set for exterior mirror rh	1.00	529.90		529.90	S
992-857-118- -	Bracket for camera lower rh	1.00	28.70		28.70	S
992-857-155-A -	Bracket for camera upper rh	1.00	28.70		28.70	S
958-980-546-00-	Camera	1.00	815.70		815.70	S
992-857-556- -	Gap sealing upper rh	1.00	38.00		38.00	S
9J1-857-680- -	gap sealing rh lower	1.00	43.50		43.50	S
958-959-578-A -	adjuster unit rh	1.00	346.20		346.20	S
9J1-821-102-CY-GR	FRONT FENDER RH	1.00	1,718.70		1,718.70	S
9J1-854-522- -G2X	FRNT FENDER COVER RH LOWER	1.00	101.70		101.70	S
9J1-854-946- -	Retainer for trim LOWER RH	1.00	53.80		53.80	S
PAD-809-964- -	Air guide FOR FENDER RH	1.00	69.00		69.00	S
9J1-854-886- -OK1	SIDE SKIRT RH	1.00	603.00		603.00	S
9J1-854-944- -	retaining strip FOR FENDER RH	1.00	34.90		34.90	S
9J1-853-802- -	Spreader rivet	9.00	62.30		560.70	S
9J1-853-755- -	Retaining clip	10.00	8.30		83.00	S

*\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.*

*\*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will vary depending on the time unit that was taken for the checking and diagnosis of your vehicle.*

*\*This estimate is valid for a period of thirty (30) days only.*

*\*Prices are subject to change without prior notice.*

## QUOTATION

**CODE:** F0001  
**CUSTOMER:** MS FIRST CAPITAL INSURANCE LTD  
**ADDRESS:** 16 RAFFLES QUAY  
 #42-01  
 HONG LEONG BUILDING  
 SINGAPORE 048581  
 ATTN:MOTOR CLAIM DEPT  
**CONTACT NO.:** 65073846  
**MODEL:** PORSCHE TAYCAN  
**CHASSIS NO.:** WP0ZZY1ZMSA01649  
**ENGINE NO.:** EBF031782  
**REG NO.:** SNT3163Y  
**REGN DATE:** 09/07/2021

**PAGE NO.:** 3  
**DOCUMENT NO.:** 662  
**DOCUMENT DATE:** 28/10/2024  
**POS ID:** ES  
**PRINTED BY:** Muhammad Nur Faiz  
**SERVICE ADV:**  
**CSP/OP CODE:** Muhammad Nur Faiz  
**DEPT:** W  
**WIP NO.:** 31553  
**REF. NO.:**  
**DATE IN:**  
**EXT. WTY:**  
**MILEAGE:** 0

**DESCRIPTION:** Body & Upholstery

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
9J1-601-025-CR-QO	Alloy wheel Black FRONT RH	1.00	6,083.00		6,083.00	S

	* GST Code	Rate	Service/Goods	GST	Before GST	GST	Total
Parts	14,085.80	O	-	-			
Surcharge	0.00	S	9.00%	26,285.80	2,365.72		
Labour	12,200.00						
Menus	0.00						
					Gross *	26,285.80	2,365.72
					Less: Deposit **	0.00	0.00
					<b>Amount Due</b>	<b>26,285.80</b>	<b>2,365.72</b>
							<b>28,651.52</b>

\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

\*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of S180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

\*\* Deposit tax invoice No.:

\*This estimate is valid for a period of thirty (30) days only.

\*Prices are subject to change without prior notice.

**Eurokars Services Pte Ltd**

Customer signature

Authorised signature

Date: