

## QUOTATION

CODE: F0001  
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD  
 ADDRESS: 16 RAFFLES QUAY  
 #42-01  
 HONG LEONG BUILDING  
 SINGAPORE 048581  
 ATTN:MOTOR CLAIM DEPT  
 CONTACT NO.: 65073846  
 MODEL: PORSCHE TAYCAN  
 CHASSIS NO.: WP0ZZZY1ZMSA01649  
 ENGINE NO.: EBF031782  
 REG NO.: SNT3163Y  
 REGN DATE: 09/07/2021

PAGE NO.: 1  
 DOCUMENT NO.: 978  
 DOCUMENT DATE: 17/02/2025  
 POS ID:ES  
 PRINTED BY: Manoj Baloo  
 SERVICE ADV: Manoj Baloo  
 CSP/OP CODE: Manoj Baloo  
 DEPT: W  
 WIP NO.: 31553  
 REF. NO.: DS/SNT3163Y/0371  
 DATE IN: 29/11/2024  
 EXT. WTY:  
 MILEAGE: 33,827

DESCRIPTION: Body & Upholstery

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
NOTES	ACCIDENT REPAIR - TP CLAIM - MS FIRST CAPITAL INS	0.00	0.00		0.00	O
INS-PANEL	TO REMOVE / REPLACE SIDE MIRROR RH,FRONT FENDER RH & ALL ACCIDENT DAMAGED BODY PARTS.TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	3,440.00	1.00		3,440.00	S
INS-PAINT-(L)	TO RESPRAY SIDE MIRROR RH,FRONT FENDER RH, FRONT BUMPER.	2,800.00	1.00		2,800.00	S
INS-PB-(L)	TO CARRY - OUT BODY CAVITY PRESERVATION.	150.00	1.00		150.00	S
INS-PB-(L)	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	680.00	1.00		680.00	S
INS-PB-(L)	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150.00	1.00		150.00	S
INS-PB-(L)	TO ISOLATE THE EV BATTERY DURING THE REPAIRS INCLUDING CHARGING OF BATTERY.	390.00	1.00		390.00	S
INS-PB-(L)	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	600.00	1.00		600.00	S
INS-PB-(L)	SUNDRIES.	20.00	1.00		20.00	S
SUB-INS	PORSCHE TAYCAN TP	120.00	1.00		120.00	S
	TO MOUNT 1 SPORT RIM AND CONDUCT WHEEL BALANCING.					
	- SUBLET 10402					
992-857-110- -OK1	SIDE MIRROR TRIM RH	1.00	434.20		434.20	S

*\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.*

*\*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.*

*\*This estimate is valid for a period of thirty (30) days only.*

*\*Prices are subject to change without prior notice.*

## QUOTATION

CODE: F0001  
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD  
 ADDRESS: 16 RAFFLES QUAY  
 #42-01  
 HONG LEONG BUILDING  
 SINGAPORE 048581  
 ATTN: MOTOR CLAIM DEPT  
 CONTACT NO.: 65073846  
 MODEL: PORSCHE TAYCAN  
 CHASSIS NO.: WP0ZZY1ZMSA01649  
 ENGINE NO.: EBF031782  
 REG NO.: SNT3163Y  
 REGN DATE: 09/07/2021

PAGE NO.: 2  
 DOCUMENT NO.: 978  
 DOCUMENT DATE: 17/02/2025  
 POS ID: ES  
 PRINTED BY: Manoj Baloo  
 SERVICE ADV: Manoj Baloo  
 CSP/OP CODE: Manoj Baloo  
 DEPT: W  
 WIP NO.: 31553  
 REF. NO.: DS/SNT3163Y/0371  
 DATE IN: 29/11/2024  
 EXT. WTY:  
 MILEAGE: 33,827

DESCRIPTION: Body & Upholstery

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD			
9J1-857-578- -OK1	SIDE MIRROR BASE COVER RH	1.00	113.00		113.00	S
992-857-538-G -OK1	SIDE MIRROR COVER LOWER RH	1.00	217.00		217.00	S
992-857-522-G -	SIDE MIRROR GLASS RH	1.00	796.00		796.00	S
9J1-857-412-C -	SIDE MIRROR BASE RH	1.00	1,025.20		1,025.20	S
992-857-556- -	Gap sealing upper rh	1.00	38.00		38.00	S
9J1-857-680- -	gap sealing rh lower	1.00	43.50		43.50	S
958-959-578-A -	adjuster unit rh	1.00	346.20		346.20	S
9J1-854-886- -OK1	SIDE SKIRT RH	1.00	603.00		603.00	S
9J1-853-802- -	Spreader rivet	9.00	62.30		560.70	S
9J1-853-755- -	Retaining clip	10.00	8.30		83.00	S
9J1-601-025-CR-QO	Alloy wheel Black FRONT RH	1.00	6,083.00		6,083.00	S
992-857-528-G -G2X	Exterior mirror housing pr	1.00	361.90		361.90	S

		* GST Code	Rate	Service/Goods	GST	Before GST	GST	Total
Parts	10,704.70	O	-		-			
Surcharge	0.00	S	9.00%	19,054.70	1,714.92			
Labour	8,350.00							
Menus	0.00							
						Gross *	19,054.70	1,714.92
						Less: Deposit **	0.00	0.00
						<b>Amount Due</b>	<b>19,054.70</b>	<b>1,714.92</b>
								<b>20,769.62</b>

\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

\*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

\*\* Deposit tax invoice No.:

\*This estimate is valid for a period of thirty (30) days only.

\*Prices are subject to change without prior notice.

**Eurokars Services Pte Ltd**

Customer signature

Authorised signature

Date: \_\_\_\_\_