

Not Authorized
21 Rm & 3850/-
Paying After Paint

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Vehicle Number : SKK 2221C

Acc: 17.9.24

S/N Parts Description

- 1 Front bumper
- 2 Front bumper reinforcement
- 3 Front bumper retainer X 2
- 4 Front bumper side grille LH
- 5 Headlamp LH
- 6 Headlamp lower bracket LH
- 7 Front fender LH
- 8 Front fender inner shield LH
- 9 Front door LH
- 10 Front door mirror LH
- 11 Front door rubber LH
- 12 Front door hinge X 2
- 13 Air duct LH
- 14 Front wheel rim LH

Unit Price Amt

Bul/cm	\$819	✓
R	\$315.70	X
ALSDIS	\$80.40	✓
SL	\$130.00	X
mg/cm	\$1,655.00	✓
CM	\$74.30	✓
B	\$726.30	✓
SL	\$188.50	X
R	\$977.60	X
R	\$864.00	X
SL	\$241.00	X
\$122.00	\$244.00	X
CM	\$107.40	✓
nd	\$938.70	✓

209

Labour

- 1 To remove and refit damaged parts \$1,000.00 550/-
- 2 To spray paint on affected parts \$1,000.00 660/-
- 3 To transfer both LH doors mechanism NA \$200.00 X
- 4 Wheel alignment \$120.00 60/-
- 5 Tuff coat on affected parts \$150.00 30/-
- 6 To realign headlamp and check wiring \$50.00 20/-

Page 1

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: