

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24110030/KMA3Q2**Date:** 07/03/2025**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100401252
Claimant Vehicle No : SND3851D **Insured Vehicle No :** SKR3807U
 Date of Loss: 29/10/2024 Nature of Claim: TP Claim No: 5920683237SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SND3851D**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 Elegance 2WD (A) Engine No: 1ZR0H62422
 Reg. Date: 27/12/2021 (Man. Year: 2021) Chassis No: MR2BE3BE800017514
 Colour: Metallic Silver Odometer: 30117 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
 Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,420.49	8,197.59	222.90	2.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,910.00	1,660.00	250.00	13.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,330.49	9,857.59	472.90	4.58
Approved Total (Overridden) (S\$)		7,800.00		
Nett Amount (S\$)	10,330.49	7,800.00	2,530.49	24.50
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 30/10/2024
 Date Inspected: 30/10/2024 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun Industrial Park A
 Singapore 768761
 Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	824.30 FL	*824.30 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	512.40 FL	*512.40 FL
3	1		*REAR BUMPER LH SIDE RETAINER	Distorted	153.50 FL	*153.50 FL
4	6		*REAR BUMPER CLIPS	Necessary	27.00 FL	*27.00 FL
5	1		*REAR BUMPER TOW COVER	Dented	22.52 FL	*22.52 FL
6	1		*REAR BOOT	Bent	1,314.90 FL	*1,314.90 FL
7	1		*REAR BOOT LOGO	Necessary	70.80 FL	*70.80 FL
8	1		*REAR BOOT OUTER MOULDING	Dented	273.50 FL	*273.50 FL
9	1		*REAR BOOT EMBLEM (COROLLA)	Necessary	80.60 FL	*80.60 FL
10	1		*REAR BOOT EMBLEM (ALTIS)	Necessary	71.70 FL	*71.70 FL
11	1		*REAR BOOT INNER LOCK	Dented	553.10 FL	*553.10 FL
12	1		*REAR BOOT INNER RUBBER	Deformed	286.80 FL	*286.80 FL
13	2		*REAR BOOT REFLECTORS	O/S Cut / N/S Cracked	2,256.00 FL	*2,256.00 FL
14	2		*REAR BOOT HINGES	*Check	197.20 FL	*- FL
15	2		*TAILLAMPS	Cracked / Dented	2,795.20 FL	*2,795.20 FL
16	1		*REAR END PANEL	Bent	932.80 FL	*932.80 FL
17	1		*REAR END PANEL INNER TOP GARNISH	Mtg Cracked	374.40 FL	*374.40 FL
18	1		*SET REVERSE SENSOR	Cut	380.60 FL	*380.60 FL
19	1		*REAR SMART KEY SENSOR	*Check	100.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	11,227.32	10,930.12
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,806.83	2,732.53
Total Parts (\$\$)	8,420.49	8,197.59

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	900.00	750.00
2	PUTTY & RESPRAY PAINTING	New	900.00	800.00
3	REMOVE & REFIX REVERSE CAMERA, REVERSE SENSOR SMART KEY SENSOR AND RESET SYSTEM	New	50.00	50.00
4	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (\$\$)			1,910.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >