



Not Withheld  
11 Sep & 4900/-  
Money After Rain

Elite AM Pte Ltd

No. 2 Yishun Industrial St 1  
Northpoint Bizhub, #02-01  
Singapore 768159  
Tel: 67545101

Kenneth  
96910663

5 days

DATE: 05-11-2024

REPAIR ESTIMATE

5/11/24

VEHICLE: SLE2974H  
MODEL: Nissan X-trail

| S/n               | Description of part                | Qty | Estimate       |            |
|-------------------|------------------------------------|-----|----------------|------------|
| 1                 | Front bonnet 1021                  | 1   | RH 1,208.37    | ✓          |
| 2                 | Front bonnet hinge LH/RH           | 2   | OLSD 173.75    | ✓ 86.87    |
| 3                 | Front bonnet insulator clip set    | 1   | nn 32.70       | ✓          |
| 4                 | Front fender 715.30                | 1   | RH 778.04      | ✓          |
| 5                 | Front fender arc garnish           | 1   | nn 218.55      | ✓          |
| 6                 | Front fender inner shield          | 1   | Pn 362.10      | X          |
| 7                 | Front fender inner shield clip set | 1   | nn 32.70       | X          |
| 8                 | Fender bracket                     | 1   | R 61.78        | X          |
| 9                 | Fender protector                   | 1   | nn 87.03       | X          |
| 10                | Front headlamp RH 2689.50          | 1   | Mycom 3,121.43 | ✓          |
| 11                | Front headlamp bracket RH 53.40    | 1   | R 87.20        | X          |
| 12                | Wheelhouse RH                      | 1   | R 282.96       | X          |
| 13                | Wheelhouse upper panel RH          | 1   | R 248.19       | X          |
| 14                | Front wheel bearing                | 1   | nn na 324.71   | ✓          |
| 15                | Front absorber                     | 1   | RH 454.09      | ✓          |
| 16                | Rim 1434.50                        | 1   | nn 1,691.57    | ✓          |
| Subtotal 1        |                                    |     |                | \$9,165.18 |
| Less 30% discount |                                    |     |                | \$6,415.62 |

| Special Nett Item |                    |   |            |
|-------------------|--------------------|---|------------|
| 17                | Wheelhouse sealant | 1 | nn 50.00   |
| 18                | Tire               | 1 | nn 280.00  |
| Subtotal 2        |                    |   | 330.00     |
| Parts Total       |                    |   | \$6,745.62 |

| Labour                 |                                                                                                     |   |            |
|------------------------|-----------------------------------------------------------------------------------------------------|---|------------|
| 19                     | To straighten and panel beating front frame members, front pillar. To remove and refit above parts. | 1 | 600.00     |
| 20                     | To putty, re-spray painting and polish affected areas.                                              | 1 | 800.00     |
| 21                     | To remove and refit front undercarriage                                                             |   | 250.00     |
| 22                     | Computerised wheel alignment                                                                        |   | 80.00      |
| Labour total           |                                                                                                     |   | \$1,730.00 |
| Parts and labour total |                                                                                                     |   | \$8,475.62 |

LAK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4501  
6001  
1406  
601