

ASS. REC. BY:

REF: LPC1

ASSIGNMENT

Kenneth

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$32k

IDAC Accident Rpt: _____

Consistent?: Yes or No

GIA / PR Seen: _____

Consistent?: Yes or No

Est. Repairs: 9-5 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV. / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLE 297414Yr Regn: 07 16Type: M.Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: NISX-TrailC.G. 1997Colour: m. Blue

A/C: _____

Insured / Std / NI / NA

Sp. Reading: 116310

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cohd: Good / Fair / Poor / BurntSteering: Inoper / Jammed / Leaked / Burnt orBrake: Inoper / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD / R/Rim or

Tyre Size: _____

F: _____

R: _____

BS / PUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 3 mmL/Bal. 6 mmL/Bal. 3 mmD.O.A. 2/11/24D.O.I. 5/11/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



: Prell. Report



: Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

: Site Insp (\$ _____)



: Interview (\$ _____)



: Tech Invs (\$ _____)



: Weekend (\$ _____)

S + RS. \$ _____

Fees

Others

Format:

Sum / I.B.I: (\$ _____)

TOTAL



Not Withstand
11 Day &
Repair After Parts

Kenneth
96910663

4-5 days

Elite AM Pte Ltd
No. 2 Yishun Industrial St 1
Northpoint Bizhub, #02-01
Singapore 768159
Tel: 67545101

DATE: 05-11-2024

VEHICLE: SLE2974H
MODEL: Nissan X-trail

REPAIR ESTIMATE

5/11/24

S/n	Description of part	Qty	Estimate	
1	Front bonnet	1	Ry 1,208.37	✓
2	Front bonnet hinge LH/RH	2	OLSD 173.75	✓
3	Front bonnet insulator clip set	1	ry 32.70	✓
4	Front fender	1	Ry 778.04	✓
5	Front fender arc garnish	1	WY 218.55	✓
6	Front fender inner shield	1	Ry 362.10	X
7	Front fender inner shield clip set	1	ry 32.70	X
8	Fender bracket	1	61.78	?
9	Fender protector	1	87.03	?
10	Front headlamp RH	1	MJCM 3,121.43	✓
11	Front headlamp bracket RH	1	87.20	?
12	Wheelhouse RH	1	R 282.96	X
13	Wheelhouse upper panel RH	1	248.19	?
14	Front wheel bearing	1	ry 324.71	?
15	Front absorber	1	454.09	?
16	Rim	1	Ry 1,691.57	✓
Subtotal 1				\$9,165.18
Less 30% discount				\$6,415.62

Special Nett Item			
17	Wheelhouse sealant	1	50.00
18	Tire	1	ry 280.00
Subtotal 2			330.00
Parts Total			\$6,745.62

Labour			
19	To straighten and panel beating front frame members, front pillar. To remove and refit above parts.	1	600.00
20	To putty, re-spray painting and polish affected areas.	1	800.00
21	To remove and refit front undercarriage		250.00
22	Computerised wheel alignment		80.00
Labour total			\$1,730.00
Parts and labour total			\$8,475.62

LKK Auto Consultants hence notify
the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4501
6001
7
601