

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

01/11/2024 18:49

OWNER'S PARTICULARS

JOB-NO: 50116501

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHC0229Y

TRANS: AUTO

CHASSIS: KMHC851CVLU183130

MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 DI

ENGINE: G4LEKU386069

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHT AND PANEL BEAT ACCIDENT AREA	1.00	1,000.00	0.00	1,000.00		Y	<u>400</u>
2 SUNDRIES	1.00	60.00	0.00	60.00		Y	<u>20</u>
3 DIAGNOSTIC(CLEAR FAULT CODE) & CHECK WIRING & LIGHTING SYSTEM	1.00	180.00	0.00	180.00		Y	<u>80</u>
4 R&R RADIATOR INNER & RADIATOR INVERTER & A/C CONDENSER	1.00	150.00	0.00	150.00		Y	<u>X</u>
5 VACUUM & TOP UP AIR COND GAS R-134A	1.00	150.00	0.00	150.00		Y	<u>X</u>
6 RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00		Y	<u>200</u>
7 RESPRAY FRONT BUMPER CENTER UPPER MOULDING	1.00	200.00	0.00	200.00		Y	<u>200</u>
8 RESPRAY FRONT BUMPER LOWER GRILLE CENTER MOULDING	1.00	150.00	0.00	150.00		Y	<u>X</u>
TOTAL:		2,140.00	0.00	2,140.00			
MATERIALS							
1 FRONT BUMPER <i>replaced</i>	1.00	430.90	86.18	344.72	L	Y	
2 FRONT BUMPER CENTER UPPER MOULDING <i>cut</i>	1.00	284.90	56.98	227.92	L	Y	
3 FRONT BUMPER RADIATOR GRILLE <i>cut</i>	1.00	708.90	141.78	567.12	L	Y	
4 FRONT BUMPER LOWER GRILLE <i>X</i>	1.00	186.90	37.38	149.52	L	Y	
5 FRONT BUMPER LOWER GRILLE CENTER MOULDING <i>X</i>	1.00	44.00	8.80	35.20	L	Y	
6 FRONT BUMPER NUMBER PLATE GARNISH <i>X</i>	1.00	22.10	4.42	17.68	L	Y	
7 FRONT BUMPER RETAINER LH <i>X</i>	1.00	28.00	5.60	22.40	L	Y	
8 FRONT BUMPER RETAINER RH <i>X</i>	1.00	28.00	5.60	22.40	L	Y	
9 FRONT BUMPER REINFORCEMENT <i>?</i>	1.00	1,075.10	215.02	860.08	L	Y	
10 FRONT BUMPER REINFORCEMENT SPONGE <i>?</i>	1.00	86.90	17.38	69.52	L	Y	
11 FRONT BUMPER TOP SEAL <i>X</i>	1.00	29.40	5.88	23.52	L	Y	
12 FRONT BUMPER TOP GARNISH <i>X</i>	1.00	48.30	9.66	38.64	L	Y	
13 FRONT BUMPER TOW CAP <i>X</i>	1.00	15.40	3.08	12.32	L	Y	
14 FRONT SUPPORT PANEL <i>X</i>	1.00	949.30	189.86	759.44	L	Y	<u>X</u>
15 FRONT BUMPER CLIP SET <i>X</i>	1.00	55.00	0.00	55.00	S	Y	<u>30</u>
16 RADIATOR COOLANT <i>X</i>	1.00	60.00	0.00	60.00	S	Y	<u>X</u>
17 FRONT NUMBER PLATE & FRAME <i>com</i>	1.00	80.00	0.00	80.00	S	Y	<u>35</u>
TOTAL:		4,133.10	787.62	3,345.48			
TOTAL PARTS & LABOUR :		6,273.10	787.62	5,485.48			

EXCESS/LOADING:S\$ 0.00

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

No. Of Day: 4 days

RE-SURVEY: BEFORE (AFTER) PAINTING
PART-BY-PART OR LUMP SUM: S\$

DATE OF SURVEY: 04 / 11 / 24 @ 1615

SURVEYED BY: Rashid - 4p 97010568

CONTACT NO: _____ FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

60190078

Ding Auto User 1

ESTIMATOR

STAAUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: